

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8148)

Set a chincapin post 3 ft. long, 3" sq., 18" in the ground, marked ¼ S on the N side, for the ¼ Sec. cor., from which

A chincapin, 12" dia., bears S.22°W., 19 lks., mkd: ¼ S BT

A chincapin, 12" dia., bears N.72°W., 39 lks., mkd: ¼ S BT

Richard C. Grant, RE 2807 - D. Powell - W. Oilar - Bob Carter - Martin Bros. Box - Jan. 21, 1958 - C.S. File 42/328-4

Renewed the ¼ corner between secs. 4 & 9 T31S R8W from the old witness trees:

The 12" Chinquapin which bears N.72°W., 39 lks., now being a broken off stump and

The 12" Chinquapin which bears S.22°W., 19 lks., being a stump hole with the uprooted stump lying near.

Set 4" hemlock post 4 ft. long for the corner & scribed 2 new trees:

A fir 16" in dia., N.18°E., 25.8 ft. mkd: ¼ T31S R8W Sec 4 2807 BT. This tree has a cruiser mark (Gilbert)

A fir 5" in dia., S.56°W., 15 ft. marked ¼ T31S R8W S9

BLM dependent resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyors and Donald R. Beck, Survey Technician, under Group #350, surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 32 Page(s) 13207-8)

The ¼ sec. cor. of secs. 4 & 9, monumented with a wooden post, 4" square, 3 ft. above ground, firmly set, at record bearing & distance from the remains of the original BTs:

A rotted and broken off chinquapin stump, bears N.72°W., 39 lks.

A stump hole, with roots and bark of a chinquapin, bears S.22°W., 19 lks.

and BTs mkd by Grant, in 1953 (Rec. on file in DCSO is 1958, JC)

A fir, 18" dia., bears N.18°E. 40 lks., with illegible scribe marks visible on partially healed blaze.

A fir, 6" dia., bears S.56°W., 23 lks., with scribe marks ¼ S9 T31S R8W visible on open blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 16" in the ground to bedrock, and in a mound of stone, 34 ft. base, to top, - with brass cap mkd.

¼ $\frac{S\ 4}{S\ 9}$

T31S R8W

1961

continued next page

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees
A fir, 38" dia., bears N.49½°E., 47 lks., mkd. ¼ S4 BT.
A hemlock, 6" dia., bears S.38½°W., 19 lks., mkd: ¼ S9 BT.

Gerald Nygren - For: Seneca Jones Timber - 4/2015 - M169-26

Found - 1961 BLM Brass cap
1958: 24" D.Fir, now stump, bears N.18°E., 26.4'
New - 14" W.Fir bears N.57°E., 13.6', scribed: "¼ S4 BT"
17" W.Fir bears S.71°E., 28.6', scribed: "¼ S9 BT"