

TOWNSHIP 31 RANGE 08 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8133)

Set a chincapin post 3 ft. long, 3" sq., 18" in the ground, for the ¼ sec. cor. mkd ¼ on N side, from which
A Laurel, 12" dia., bears S.4°W., 34 lks., mkd: ¼ S BT.
A Fir, 12" dia., bears N.45°W., 39 lks., mkd: ¼ S BT.

Reported as not fd., DCSO JMP, 3/1970 - C.S. File 54/36-40

Douglas Co. Surveyors Office - Gary L. Langlitz - Pete Earle - Karen Cheney - Oct. 19, 1976 - C.S. File 59/24-38

Found - The orig. NW BT, an orig. 12" now 22" D.Fir, alive and in good condition, with scribing "¼" visible on previously opened blaze.
The orig. corner monument, a Chinquapin post and the SW BT are gone.

At the corner point as determined by the record measurements from the found Orig. BT, an orig. 12" now 22" D.Fir as described above, bearing N.45°W., 25.7 ft.

We set a 1"x30" I. pipe _____ in the ground with brass cap attached mkd: DOUGLAS CO. SURVEYOR T31S R8W
1976 $\frac{S\ 22}{S\ 27}$ ¼

New BT - A 22" D.Fir bears S.9°E., 45.7 ft. scribed "¼ S27 CS BT" on a double blaze.

FD. & used on BLM Dependent resurvey by James E. Jelley and James J. Carlson, Cadastral Surveyors under Group #899, surveyed Aug. 1976/Nov. 1977 - (DCSO Recs Vol. 41 Page 16206)