

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 19 Page(s) 8126)

-----  
Set a stone 14x12x10", 8" in the ground, for the 1/4 sec. cor. mkd 1/4 on the W face, from which  
A fir, 24" dia., bears S.75°E., 18 lks., mkd: 1/4 S BT.  
A live oak, 10" dia., bears N.60°W., 14 lks., mkd: 1/4 S BT.

BLM dependent resurvey by C. Albert White, Harold D. Corbin, Cadastral Surveyors and Donald R. Beck, Survey Technician, under Group #350, surveyed Nov. 1960/Sept. 1962 - (DCSO records Vol. 32 Page(s) 13194)

-----  
The sec. cor. of secs. 14 and 15, monumented with a granite stone, 14x12x8", no marks visible, loosely set in a small mound of stone, from which the remaining original BT:

A fir, 35" dia., bears S.75°E., 20 lks. (18 lks. to face), marked with illegible bark scribing on double bark blaze. (Record distance, 18 lks.) Remarkd 1/4 S14 BT.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 21" in the ground, and in mound of stone, 3 ft. base, to top, with brass cap mkd.

1/4  
S 15 | S 14  
T 31 S | R 8 W  
1962

from which a new bearing tree

A fir, 15" dia., bears N.25°W., 72 lks., Mkd. 1/4 S15 BT.  
Deposit original corner stone alongside iron post.

Mark Smalley - For: Roseburg Resources - 2/28/2001 - C.S. File 65/37-26

-----  
Found - 1962 BLM IPBC  
35" Fir, S.75°E., 13.2 good condition - face had been chopped out and grown over (rec. 1977 - 40", (orig. 11.9 ft.)  
20" Fir, N.25°W., 47.5 good condition - face had been chopped out and grown over.  
Both BTs: Were measured twice to verify the 35" BT & the 20".

New BTs- 11" Live Oak N.38°W., 11.0 scribed "1/4 S BT"  
8" Live Oak S.26°E., 25.7 scribed "1/4 S BT"