

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25, T31-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8175)

-----  
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S S25 on W.; S30 on E. faces, from which  
A Fir 36" dia., bears N.75°E., 250 lks. mkd. S30 1/4 S BT.  
A Cedar 36" dia., bears N.48°W., 224 lks. mkd. S25 1/4 S BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - April/May 1967 - C.S. File 54/32-74

-----  
Found - Old scribed stake "1/4S" visible & 3/4" I.Pipe, badly rusted.

36" Cedar now snag, N.48°W., 147.8 ft scribe visible NE. BT falls in logged area and skid trails.

Set Brass cap at cor. mkd: County Surveyors Office

R T 31 S R  
10 1/4 S 25 | S 30 9  
W 1967 W

New BTs- 12" D.Fir S.29°W., 18.6 ft. mkd. 1/4 S25 CS BT.  
10" Cedar N.51°E., 14.5 ft. mkd. 1/4 S30 CS BT.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/19/2015 - C.S. File 65/87-62

-----  
Found - 2 1/2" brass cap on a 1 1/4" O.D. iron pipe, 1.0' tall, in good condition and solid in the ground, leaning slightly to the South. We find a 1" iron pipe, 2.05' tall, of unknown origin, fd by Powell in 1967, S.78°E., 0.35'. We set a D.Fir post 2' North and paint the top in blue. There is a broken off wood post 1' North of the BCIP.

1900: 35" W.Cedar snag, 30' tall, N.45°15'W., 149.44' to left side center. We find visible scribes and a 1958 BLM tag in place. We paint the face and a band around the snag in blue. Snag falls near an old logging road. GOOD CONDITION

1900: 17" W.Cedar, N.52°30'E., 14.58' to right side center. We find a healed blaze but no tag. We paint the blaze and a band around the tree in blue and attach a new yellow tag. GOOD CONDITION

Laush Tag 1950 (unrecorded): 15" D.Fir with top broken and touching the ground, yet still attached to the main stem, N.85°E., 10.69' to left side center. There is a healed scar on the right side. We paint the scar and a band around the tree in blue. FAIR Condition.

Cont. next pg

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25, T31-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

New - 9" D.Fir, S.35°W., 33.37' to a nail at right side center. We blaze and scribe "¼ S25 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos County tag.  
7" D.Fir, N.41°W., 27.96' to a nail at left side center. We blaze and scribe "¼ S25 BT". We paint the blaze, scribed, and a band around the tree in blue and attach a yellow Coos County tag.  
4" D.Fir, S.44°E., 25.65' to a nail at left side center. We chop a notch low and scribe an "X" high. We paint the notch, "X" & a band around the tree in blue and attach a yellow Coos County tag.  
Decl. 17°E.

Fd. BC & BTs as per rec. 4/2015 by T. Hostetter M169-54

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 4-16-2025 - C.S. File 67/60-24

-----  
Found - 2½" brass cap (properly mkd) on iron pipe, D.C.S.O. 16"X3' Sawn W.Cedar stump N.51°E. (Rec N.52°30'E.) 14.58 ft.  
15" D.Fir broken top N.84°E. 10.5' (Rec N.85°E. 10.69')  
12" D.Fir S.33½°W. 33.5' (Rec S.35°W. 33.37') to nail right side center.  
9" D.Fir N.42½°W. 27.96' (Rec N.41°W.) Nail right side center, fully healed single blaze.  
5" D.Fir S.45°E. (Rec S.44°E.) 25.65' to nail right side center.  
Coos County used a 17° declination. Should have been a 15°.

Notes - Mon is on flat ground on edge of older reprod. Uneven clearcut. Edge to north and east.

Compass decl. 14½°E.  
Lat. 42°50'45.623 N Long. 123°49'09.591 W