

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19; & 24, T31-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8176)

-----  
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for the ¼ sec. cor. mkd. S19 ¼ S on E.; and S24 ¼ S on W. faces, from which

A Fir 8" dia., bears N.62°E., 13 lks. mkd. S19 ¼ S BT.  
A Fir 30" dia., bears N.78°W., 40 lks. mkd. S24 ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1967 - C.S. File 54/32-77

-----  
Found - Orig. 8" now 12" D.Fir, N.62°E., 8.6 ft., shows scar.

Orig. 30" now 34" D.Fir, now down, N.78°W., 26.4 ft., opened for scribe "4 S".

Set Brass cap at cor. mkd: County Surveyors Office

R T 31 S R  
10 ¼ S 24 | S 19 9  
W 1967 W

New BT - 7" Hemlock S.85°W. 21.6 ft. mkd. ¼ S24 CS BT.

BLM Resurvey by Francis J. Simon, Cadastral Surveyor, under Group #1679, Surveyed July/Oct. 1993 - (DCSO records Vol. 51 Page(s) 19556)

-----  
The ¼ sec. cor., perpetuated and recorded by DCSO in 1967, determined at record bearing and distance from the remaining original bearing tree, alongside of which is lying an iron post, 1½" dia., 30" long, with brass cap mkd. as described, from which the remaining original bearing tree:

A Fir 16" dia., bears N.62°E., 13 lks., no marks visible on scarred trunk.

At the corner point

RESET the DCSO Iron post, 27" in the ground with brass cap as marked in 1967,

from which a new bearing tree

A Fir 7" dia., bears N.86°W., 54 lks. mkd. ¼ S24 BT.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/17/2015 - C.S. File 65/87-60

-----  
Found - 2½" brass cap on an 1½" O.D. iron pipe, 0.25' tall, in good condition and solid in the ground. We set a D.Fir post 3' North and paint the top in blue.

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19; & 24, T31-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1901: 21" D.Fir, N.66°E., 8.50' to right side center. We find a large healed scar facing the corner with a Coos Bay Lumber tag in place. We paint the face and a band around the tree in blue. GOOD

1993: 10" D.Fir, N.84°W., 35.65' to left side center. We find a healed blaze, but no tag. We paint the face and a band around the tree in blue and attach a new yellow tag. GOOD CONDITION

New - 18" W.Cedar stump, S.58°E., 13.65' to a spike and Coos County washer driven in at heart center. We chop an "X" in the face and paint the "X" and the top of the stump in blue and attach a yellow Coos County tag.

4" D.Fir, N.34°30'W., 10.39' to a nail at right side center. We blaze and scribe "BT" low and "X" high. We paint the blaze, scribes "X" and a band around the tree in blue and attach a yellow Coos County tag.

Decl. 17°

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/3/2025 - C.S. File 67/60-11

-----

Found - 2½" D.C.S.O. brass cap proj 2"  
24" D.Fir N.66°E. 8.5' healed face. Add 3½" mag nail right side center.  
11"x7' sawn D.Fir stump N.85°W. (Rec N.84°W.) 35.65' to fd nail left side center. Healed blaze.  
18"x2' W.Cedar stump S.59½°E. (Rec S.58°E.) 13.65' to a spike and Coos County was top center.  
Root hole with tipped out 5" D.Fir N.34½°W. 10.39' with fully healed blaze.

New - 12"x1' Hemlock stump N.21½°E. 25.2'. 3½" mag nail top center.

Notes - Mon on relative flat ridge top. Older reprod to east. New and older clear cuts to west.

Compass decl. 14½°E.  
OCRS COORDINATE SYSTEM  
COTTAGE GROVE-CANYONVILLE ZONE  
N 10291.640 E 33749.227