

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T31-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8176)

Set a Cedar post 4 ft. long, 4" sq., 24" in ground, for cor. of secs. 13, 18, 19 and 24, mkd. T31S S18 on NE.; R9W S19 on SE.; R10W S24 on SW.; and S13 on NW. faces, with 3 notches on N. and S. angles, from which
A Fir 48" dia., bears S.35°E., 13 lks. dist. mkd. T31S R9W S19 BT.
A Cedar 8" dia., bears N.65°E., 48 lks. dist. mkd. T31S R9W S18 BT.
A Fir 40" dia., bears S.32°W., 28 lks. dist. mkd. T31S R10W S24 BT.
A Fir 24" dia., bears N.88°W., 33 lks. dist. mkd. T31S R10W S13 BT.

T.H. Mehl, III - For: The Robert Dollar Co. - Oct. 12, 1966 - C.S. File 55/15-2

Found - Corner in poor condition.
48" Fir BT, S.35°E., 8.6 ft., now high stump.
8" Cedar BT, N.65°E., 31.7 ft., removed in logging.
40" Fir BT, S.32°W., 18.5 ft., now high stump.
24" Fir BT, N.88°W., 21.8 ft., now snag stump.
For the cor., I Set a 1½" x 30" Iron pipe, 28" in the ground.
New BTs- 5" Hemlock N.26°W., 8.2 ft. scribed S13 RS749 BT.
4" Hemlock N.6°E., 5.1 ft. scribed X BT. at breast height.
12" W.Fir S.30½°W., 52.5 ft. scribed S24 RS749 BT.
13" Cedar S.25½°E., 51.9 ft. scribed S19 RS749 BT.
Reference done with staff compass and chain.

BLM resurvey by Francis J. Simon, Cadastral Surveyor, under Group #1679, Surveyed July/Oct. 1993 - (DCSO records Vol. 51 Page(s) 19557-58)

The Sec. Cor., perpetuated and recorded by Mehl, in 1966, monumented with an iron pipe 1½" dia., firmly set, projecting 2" above the ground, from which the remains of the original bearing trees:
A sawed Fir stump 38" dia., bears S.35°E., 13 lks. dist., with healed blaze.
A sawed Fir stump 36" dia., bears S.32°W., 28 lks. dist., with healed blaze.
and bearing trees mkd. by Mehl
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T31-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A shattered stump bears N.6°E., 8 lks. dist., alongside of which is a Hemlock 6" dia., with scribe marks X BT visible on open double blaze.

A Cedar 22" dia., bears S.26°E., 79 lks. dist., with healed blaze.

A decomposed stump bears S.30½°W., 79½ lks. dist., with illegible scribe marks visible on rotted blaze.

A Hemlock 11" dia., bears N.27 3/4°W., 12½ lks. dist., with healed blaze.

At the corner point

Set an stainless steel post, 28" long, 2 1/2" dia., directly over the iron pipe, 24" in the ground, with brass cap mkd:

T 31 S
R10W R9W
S 13 | S 18
S 24 | S 19
1993

from which new bearing trees

A W.Fir 7" dia., bears N.75¼°E., 19½ lks. dist. mkd. T31S R9W S18 BT.

A Fir 9" dia. bears S.42¼°W., 44½ lks. dist. mkd. T31S R10 S24 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/16/2015 - C.S. File 65/87-59

Found - 1993 3¼" brass cap on a 2½" stainless steel pipe, 0.4' tall, in good condition and solid in the ground, in new clear cut. We set a cedar post 2' north and paint the top in blue.

1901: 34" D.Fir stump, S.30°E. 9.69' to heart center We find a healed blaze with no visible marks or tags. We paint the face in blue. FAIR COND.

1901: 36" D.Fir stump, 4' tall, S.34°W., 19.90' to heart center. We find visible scribes in a partly healed blaze. We paint face in blue. POOR

1966: 13" hemlock tall stump, 8' tall N.26°W., 8.20' to right side center. We find a healed blaze with a BLM tag in place. We paint the face and a band around the stump in blue. GOOD CONDITION

1966: 13" Hemlock tall stump, 6.5' tall, N.77°E., 12.95' to right side center. We find a healed blaze with a BLM tag in place. We paint the face and a band around the stump in blue. GOOD CONDITION.

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T31-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

1966: 15" D.Fir tall stump, 6.5' tall, S.44°W.,
28.80' to right side center. We find a healed
blaze with a BLM tag in place. We paint the face
and a band around the stump in blue. GOOD
CONDITION

Note - 22" Cedar, SE BT per (C.S.) 55/15 is gone;
12" Hemlock, SW BT per (C.S.) 55/15 is gone;
6" Hemlock snag, NE BT (C.S.) 55/15 is down, tag in
place.

New - 15" D.Fir stump, 1' tall S.5°E., 14.44' to a spike
and Coos County washer driven in at heart center.
We chop an "X" in the face, and paint the "X" and
the top of the stump in blue and attach a yellow
Coos County tag.
decl. 17°E.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 3/4/2025 - C.S. File 67/60-12

Found - 3/4" BLM brass cap proj 0.4' solid.
Very rotted 34"x2½' fir stump S.33°E. 9.69' to heart
center face in poor condition (rec S.30°E.)
36"x4' D.Fir stump S.32°W. (rec S.31°W.) 19.9' to
center. Visible scribes. Face in fair cond.
13"x8' Hemlock stump N.26°W. 8.2' healed blaze.
13"x6.5' Hemlock stump N.75°E. (rec N.77°E.) 12.95'
healed blaze.
15"x6.5' D.Fir stump S.42°W. (rec S.44°W.) 28.8'
healed blaze.
15"x1' D.Fir stump S.6½°E. (Rec S.5°E.) 14.44'.
Spike in heart center with Coos County washer
with "X" in face. Bearing diff due to difference
in decl.

Notes - Mon is in newer clearcut unit. Approx 90' west of
gravel road.
Compass decl. 14½°E.
OCRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N 12928.889 E 33794.641