

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T31-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8177)

-----

Marked a Fir 50" dia., T31S S7 on NE.; R9W S18 on SE.; R10W S13 on SW.; and S12 on NW. faces; also 2 notches on N. and 4 on S. for the cor. of secs. 7, 12, 13, and 18, from which  
 A Fir 50" dia., bears N.42°E., 54 lks. dist. mkd. T31S R9W S7 BT.  
 A Fir 40" dia., bears S.60°E., 52 lks. dist. mkd. T31S R9W S18 BT.  
 A Fir 10" dia., bears S.50°W., 66 lks. dist., mkd. T31S R10W S13 BT.  
 A Fir 36" dia., bears N.55°W., 31 lks. dist., mkd. T31S R10W S12 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1967 - C.S. File 54/32-78

-----

Found - Corner tree, now stump, shows good scars.  
 50" D.Fir now stump, N.42°E., 35.6 ft., shows good scars.  
 40" D.Fir now stump, S.60°E., 34.3 ft., shows good scars.  
 10" D.Fir now 14" stump, N.55°W., 43.6 ft., opened for scribe "BT"  
 36" D.Fir now 38" stump N.55°W., 20.5 ft., shows good scars.

Set brass cap on N. side of Corner tree stump. **(B.C. lies 4.0 ft. N. of center of stump)** Cap mkd. County Surveyors Office

R	T	31	S	R
10	S	12	S	7
W	S	13	S	18
1967				

New BTs- 12" Chinquapin S.22°E., 133.2 ft. mkd. T31S R9W S18 CS BT.  
 14" Hemlock S.12°W., 146.7 ft mkd T31S R9W S13 CS BT  
 No other trees available  
 Location tag on 36" Fir stump, S.41°W., 60.7 ft. on skid trail.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/10/2015 - C.S. File 65/87-58

-----

Found - Orig. corner tree; 40" D.Fir stump with some solid wood 4' tall with scribes on the NE, South and West sides. **We paint** the scribe areas in blue.

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

1967 2½" brass cap on a 1¼" O.D. iron pipe, 0.7' tall, in good condition and solid in the ground, 4.0' north of the corner tree stump. **We set** a D.Fir post 3' north of the BCIP and **paint** the top in blue.

**The following measurements are taken from the BCIP monument:**

1901: 40" D.Fir stump, N.39°30'E., 19.45' to heart center. We find visible scribes with a Douglas Co. tag in place. **We paint** the face and a band in blue. POOR

1901: 39" D.Fir stump, 5' tall, N.58°W., 18.13' to heart center. We find visible scribes in a mostly healed offset blaze. **We paint** the face in blue. FAIR

1901: 30" D.Fir stump, S.57°E., 36.74' to heart center. We find visible scribes with a Douglas Co. tag in place. **We paint** the face and "BT" in blue. POOR

1967: 30" hemlock, S.17°W., no distance measured. We find visible scribes in a mostly healed blaze. **We paint** the face and a band around the tree in blue. Tree has rotten heart but is in FAIR CONDITION.

1967: 21" Chinkapin, S.19°E., 136.15' to side center. We find a healed offset blaze and tag nails in place. **We paint** the face and a band around the tree in blue. Tree is alone in clear cut. GOOD CONDITION.

**New -** 16" D.Fir low cut stump, S.82°W., 21.22' to a spike and Coos County washer driven in at heart center. We chop an "X" in the face and paint the "X" and the top of the stump in blue and attach a yellow Coos County tag.

23" D.Fir low cut stump, N.8°W., 6.02' to a spike and Coos County washer driven in a heart center. We chop an "X" in the face and paint the "X" and the top of the stump n blue and attach a yellow Coos County tag.

19" D.Fir low cut stump, S.63°E., 19.31' to a spike and Coos County washer driven in a heart center. We chop an "X" in the face and paint the "X" and the top of the stump n blue and attach a yellow Coos County tag.

decl. 17°E