

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & S. 1, T31-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8179)

Set 2 basalt stones each 10x6x5 ins., 7" in the ground, mkd. ¼, from which
A Hemlock 6" dia., bears N.62°E., 9 lks. dist. mkd. S6 ¼ S BT.
A Fir 24" dia., bears N.45°W., 20 lks. dist. mkd. S1 ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - March 1967 - C.S. File 54/32-45

Found - 6" Hemlock, now snag, N.62°E., 5.9 ft. scribe visible "¼ S BT".
24" D.Fir now stump, N.45°W., 13.2 ft., scribe visible "¼".

Also, unrecorded I. Pipe at ¼ corner.
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S
R10W ¼ S 1 | S 6 R9W
1967

New BTs- 10" Cedar N.47½°E., 23.7 ft. mkd. ¼ S6 CS BT.
13" Cedar S.53°W., 79.4 ft. mkd. ¼ S1 CS BT.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/4/2015 - C.S. File 65/87-55

Found - 2½" brass cap on a 1¼" o.d. iron pipe, 0.7', in good condition and solid in the ground. We find an unrecorded 1¼" iron pipe 1.3' tall in the north side of the BCIP. We set a White Cedar post 3' North a paint the top in blue.

1900: 24" D.Fir tall stump, 5' tall, N.42°30'W., 13.33' to heart center. We find visible scribes in a partly healed blaze. We paint the face and "BT" in blue. Poor Condition.

1967: 13" W.Cedar, N.50°E., 24.29' (N.47°30'E., 23.7' rec.) to right side center. We find visible scribes in a partly healed blaze with a Douglas Co. tag in place. We paint the face and a band around the tree in blue. Good Condition

1967: 24" W.Cedar stump, S.54°W., 79.50' to heart center. We open the face and find visible scribes. We paint the face and the top of the stump in blue. Good Condition.

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & S. 1, T31-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Unrecorded: 8" W.Cedar snag, S.20°W., 17.0' to right side center. We find a high offset blaze with no visible scribes and a Coos Bay Lumber tag in place. We paint the face in blue. Snag is solid and in Good Condition.

New - 8" D.Fir S.69°30'W., 9.88' to a nail at left side center. We blaze and scribe "¼ S1 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos County tag.

15" D.Fir, N.35°W., 20.24' to a nail at right side center. We blaze and scribe "¼ S BT" We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos County tag.

Compass declination: 17°E