

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8223)

-----  
A Live Oak, 4" dia., mkd S29 ¼ S on N and S 32 ¼ S on S sides for the ¼ Sec. cor. from which

A live Oak, 8" dia. bears N.20°E., 19 lks. mkd: S22 ¼ S BT  
A fir, 18" dia., bears S.48°W., 44 lks., mkd: S32 ¼ S BT.

-----  
Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Joe Brady - March/April 1967 - C.S. File 54/32-63

-----  
Found - No trace of 4" Live Oak corner tree.  
8" Live Oak, now 10" N.20°E., 12.5 ft. 2 good faces.  
18" D.fir now 24" stump, S.48°W., 29.0 ft. opened & fd good "BT" scribe.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T31S R9W  
OFFICE ¼ S 29  
1967 S 32

New BT - 7" Live Oak S.32°W., 16.8 ft. mkd: ¼ S32 CS BT.

Note - Corner lies on steep, west slope.