TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8231-2)

Mark a cedar, 12" dia., S8 ¼ S on N & S17 ¼ S on S faces for the ¼ sec. cor. from which
A fir, 12" dia., bears N.40°E., 14 lks., mkd: S8 ¼ S BT.
A cedar, 12" dia., bears S.50°W., 41 lks. mkd: S17 ¼ S BT.

Clifford A Stephens - For: Coos Head Timber Co - 3/18/1959 - C.S. file 51/178 & M20-16

From BTs fd. - Set post ¾" iron pipe for ¼ corner from which:
12" Fir bears N.51°E., 9.2 ft., scribing visible.
12" Cedar bears S.45°W., 27.1 ft., down.
24" Fir bears S.40°E., 15.0 ft. (New BT)

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & Joe Brady - March 1967 - C.S. File 54/32-50

Found - ¾" Iron pipe at ¼ corner.
24" D.Fir, now stump, S.40°E., 15.0 ft., scribe visible "BT" ¼S" S17 T31S"
12" D.Fir, now rotten stump, N.51°E., 9.2 ft.
Set Brass cap alongside IP mkd: COUNTY SURVEYORS OFFICE 1967 T31S R9W ¼ S 8 / S 17
New BTs- 9" hemlock S.77°W., 41.0 ft., mkd: ¼ S17 CS BT.
No other trees available.
Note - This corner lies about 150.0 ft. S of road on Gold Creek.
Location tag on road.