

PRIMARY CORNER DESCRIPTION Cor Secs 21, 22, 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8203-4)

Mark a Fir, 8" dia., for T31S S22 on NE, R9W S27 on SE, S28 on SW and S21 on NW faces, also 2 notches on S & 3 notches on E side of same for the corner of secs. 21, 22, 27 & 28 from which

A fir, 10" dia., bears N.25°E., 106 lks., mkd: T31S R9W S22 BT.

A fir, 8" dia. bears S.72°E., 55 lks. mkd: T31S R9W S27 BT

A fir, 8" dia. bears S.40°W., 22 lks. mkd: T31S R9W S28 BT

A fir, 16" dia., bears N.68°W., 100 lks., mkd: T31S R9W S21 BT.

Not fd by J.P. DCSO, 8/10/1970: This area very badly burnt. All young reprod. For line came off ¼ S22 & S27. C.S.54/32-97 & C.S. 53/53-21

BLM dependent resurvey by Lynn M Roseberry, Cad. Surveyor, Group #882, surveyed Aug. 1973 - (DCSO recs Vol 37 Pg 15325)

The cor. of secs. 21, 22, 27, & 28, determined at record bearing and distance from the remains of the original BTs:

A burned and decayed fir stump, 16" dia., bears N.68°W., 100 lks., no marks visible on a badly burned & decayed detached blaze lying alongside.

At the corner point

Set an iron post, 28" long 2½" dia., 24" in the ground, with brass cap mkd.

T31S	R9W
S 21	S 22
S 28	S 27

1973 from which new BTs

A fir, 13" dia., bears N.17½°E., 22 lks., mkd: T31S R9W S22 BT.

A fir, 14" dia., bears S.64¾°E., 68 lks., mkd: T31S R9W S27 BT.

A fir, 10" dia., bears S.62½°W., 42½ lks., mkd: T31S R9W S28 BT.

A fir, 9" dia. bears N.45°W., 47½ lks mkd: T31S R9W S21 BT

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2796, surveyed Aug. 2015/March 2016 - (DCSO records Vol. 58 Page(s) 23440-2 & Plat T31-9 2017-1)

The cor. of secs. 21, 22, 27, & 28, monumented with an iron post, 2½" dia., firmly set, projecting 7" above ground, with a brass cap (properly) mkd.

continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor Secs 21, 22, 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the BTs mkd. by Roseberry in 1973
A roothole bears N.17½°E., 14.5 ft., alongside of which is
a down fir, 23" dia., no marks visible.
A roothole bears S.64¾°E., 44.9 ft. dist, alongside of
which is a down fir, 17" dia., no marks visible.
A decayed fir stump, 23" dia., bears S.62½°W., 28.1 ft.,
with remains of a healed blaze.
A decayed fir stump, 13" dia., bears N.45°W., 31.4 ft., no
marks visible.
and new accessories
A fir, 19" dia., bears N.80°E., 68.3 ft., mkd. T31S R9W
S22 BT.
A fir, 24" dia., bears S.50°E., 72.4 ft., mkd. T31S R9W
S27 BT.
An iron rod, 30" long, 5/8" dia., set 26" in the ground
for a reference monument, bears S.23°45'40"W., 17.50
ft., with aluminum cap mkd. RM T31S R9W 17.5 FT TO COR
S28 2015, and an arrow pointing to the cor.
A fir, 7" dia., bears N.44¼°W., 54.0 ft., mkd, X BT.
Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven
at the base on right side center
Corner is located in fallen trees near the NE. cor. of
timber, edge bears S. and E.; younger fir reproduction to the
N. and W.