

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 424100

PRIMARY CORNER DESCRIPTION A P on S. Bdy. Sec. 34

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records C.S. File 64/76-2)

-----  
A Fir 10" dia., which I marked T31S R9W S34 in NE.; T32S S3 on SE.; S4 on SW.; and S32 on NW. faces, also 3 notches on the E. and W. angles of same for the cor. to secs. 3, 4, 33 and 34, and from which

- A Fir 60" dia., bears N.32°E., 42 lks. mkd T31S R5W S34 BT
- A Fir 50" dia., bears S.50°E., 23 lks. mkd. T32S R9W S3 BT
- A Fir 18" dia., bears S.30°W., 24 lks. mkd. T32S R9W S4 BT
- A Fir 15" dia., bears N.45°W., 11 lks. mkd T31S R9W S33 BT

GL0 survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Pg 8170)

-----  
Old cor. of secs. 3 and 4. Corner and witness trees standing and agreeing with notes furnished by the Surveyor general.

GL0 Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12190)

-----  
Intersect at the old cor. of secs. 3 and 4, which is a rotten stump of a Fir tree, 10" dia., marked and witnessed as described by the surveyor general, with the exception that both bearing trees to the N. are dead and fallen. I change this cor. to an angle point and perpetuate it as follows: alongside the stump of the old cor. tree:

Set an iron post 3 ft. long. 1" dia., 26" in the ground, for angle point, with brass cap mkd. A P

1917

from which

- A Fir 60" dia., bears N.61°E., 46 lks. dist. mkd. AP BT.  
(New BT)
- A Fir 24" dia., bears S.76°W., 25 lks. dist. mkd. AP BT.  
(Old BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - March 1967 - C.S. File 54/32-37

-----  
Found - GL0 1917 brass cap.  
60" D.Fir now stump, N.61°E., 30.4 ft., opened for scribing "BT".

24" D.Fir now snag, S.76°W., 16.5 ft., shows scar.  
New BTs- 8" Yew S.61°W., 77.8 ft. mkd. "A P CS BT".  
9" D.Fir N.30°W., 59.7 ft. mkd. "A P CS BT".

(Cont. Next Page)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Logging road bears North 65.0 ft.  
This corner is 141.2 ft. East of Sec. Cor. to 3 & 4 only,  
T32-9

Tony Hostetter - For: Plum Creek Co. - Jan. 22, 2009 - C.S.  
File 65/66-13

-----  
Found - 1917 GLO brass cap as described by Mensch and Sorrels (vol. 29, pgs 12190). From which:  
60" fir stump, face evident, BLM tag, bears; N.61°E., 30.4 feet to center.  
24" fir snag, no marks, BT marked by Mensch in 1917 bears; S.76°W., 16.5 ft to center.  
New BTs- 16" fir, scribed "S34 AP BT", BT tag, bears N.03°E., 42.4 feet to 20D spike placed in root collar below scribing.  
14" fir, scribed "S34 AP BT", BT tag, bears S.73°E., 3.3 ft. to 20D spike placed in root collar below scribing.  
18" fir, scribed "S34 AP BT", BT tag, bears S.01°E., 13.4 ft. to 20D spike placed in root collar below scribing.  
16" fir, scribed "S34 AP BT", BT tag, bears N.14°W., 37.8 ft. to 20D spike placed in root collar below scribing.

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2862; Surveyed Nov./Dec. 2016 - (DCS0 records Vol. 59 Page(s) 23583-4)

-----  
The angle point bet. secs. 3 & 34, perpetuated by the Douglas County Surveyor's Office in 1967, and further perpetuated by Hostetter, in 2009, monumented with an iron post, 1" dia., firmly set, projecting 14" above the ground, with brass cap (properly) mkd.  
from which the remains of an original bearing tree  
A broken off and rotted fir stump, size indeterminate, bears S.76°W., 16.5 ft., with a portion of healed blaze visible.  
and the remains of a BT mkd. by Mensch and Sorrels in 1917  
A sawed and rotted fir stump, 64" dia., bears N.61°E., 30.4 ft., with scribe marks AP BT visible on exposed face.  
and the remains of bearing trees mkd. by the Douglas County Surveyor's Office  
A yew, 10" dia., bears S.61¾°W., 77.1 ft., with a healed blaze.  
continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 424100

PRIMARY CORNER DESCRIPTION A P on S. Bdy. Sec. 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A sawed and rotted fir stump, 15" dia., bears N.29½°W., 60.0 ft., no marks visible.  
and the remains of bearing trees mkd. by Hostetter  
A sawed fir stump, 14" dia., 7 ft. tall, bears N.2¾°E., 43.4 ft., with scribe marks S34 AP BT visible on partially healed blaze and a spike in the face.  
A fir, 18" dia., bears S.73¾°E., 4.6 ft., with a healed blaze.  
A fir, 22" dia., bears S.1¾°E., 15.0 ft., with a healed blaze and a spike in the face.  
A sawed fir stump, 17" dia., 7 ft. tall, bears N.13¾°W., 38.8 ft., with scribe marks S34 AP BT visible on partially healed blaze and a spike in the face.