

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION Cor. Secs 22, 23, 26, & 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8193)  
-----  
A fir, 16" dia., marked T31S S23 on NE, R9W S26 on SE, S27 on SW and S22 on NW faces, also 2 notches on E & S sides for cor. of Secs. 22, 23, 26, & 27, from which  
A fir, 12" dia. bears N.70°E. 31 lks. mkd: T31S R9W S23 BT  
A fir, 10" dia. bears S.55°E. 58 lks. mkd: T31S R9W S26 BT  
A fir, 20" dia. bears S.18°W. 44 lks. mkd: T31S R9W S27 BT  
A fir, 12" dia. bears N.18°W. 38 lks. mkd: T31S R9W S22 BT

Douglas Co. Surveyors Office - John M. Powell - Frank Jones, C. Stone & J. Brady - Feb/March 1967 - C.S. File 54/32-18  
-----  
Found - No trace of Corner Tree.  
12", now 14" Fir, N.70°E., 20.5 ft., good face.  
10" D.Fir, now down, S.55°E., 38.3 ft., opened for scribing.  
20" Fir Stob S.18°W., 29.0 ft. good face.  
12" Fir N.18°W., 25.1 ft., gone.  
Set - Brass Cap at Cor. mkd: County Surveyors T31S R9W  
Office S 22 | S 23  
1967 S 27 | S 26  
New BTs- 10" Cedar N.30°W., 101.3 ft. mkd. T31S R9W S22 CS BT  
6" W.Fir S.36°W., 39.2 ft. mkd. T31S R9W S27 CS BT.  
6" Cedar S.42°E., 11.2 ft. mkd. T31S R9W S26 CS BT.