

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8194)

Set a yew post, 4 ft. long, 4" sq., 24" in the ground, marked S23 ¼ S on N and S26 on S faces for ¼ sec. cor. from which
A fir, 18" dia., bears S.15°E., 47 lks., mkd: S 26 ¼ S BT.
A fir, 20" dia., bears N.38°W., 18 lks., mkd: S 23 ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones, C. Stone & J. Brady - Feb/March 1967 - C.S. File 54/32-17

Found - Orig. 18" Fir, now Stump, S.15°E., 31.0 ft. This stump has been moved because, of ravine road, shows scar.
Orig. 40" Fir, now down, N.38°W., 11.9 ft., opened for scribing, "T".
Set - Brass cap at Cor. mkd: County Surveyors Office 1967 T31S R9W ¼ S 23 S 26
New BT - 24" D.Fir N.55°W., 36.5 ft. mkd. ¼ S23 CS BT.
50" Fir Stump S.84°W., 39.4 ft. mkd. ¼ S CS BT.
No other tree. available.
Note - Corner lies about 25.0 ft. north of skid road & about 50 ft. east to ravine.