

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8168)

Marked a Fir 50" dia., T31S S36 on NE.; R9W S35 on NW.; and one notch on E. and five notches on W. sides, for the cor. of secs. 35 and 36. No trees within limits for witness trees.

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12188)

Intersect at the cor. of secs. 35 and 36, T31S R9W, which is a Fir tree, 50" dia., mkd. as described by the surveyor general. I mark bearing trees for this cor., as follows:

- A Live Oak 8" dia., bears N.74°E., 26 lks. dist. mkd. T31S R9W S36 BT.
- A Fir 14" dia., bears N.15°W., 69 lks. dist., mkd. T31S R9W S35 BT.