TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8184-5)

Set a cedar post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 13, 14, 23, & 24, marked T31S S 13 on NE, R9W S 24 on SE, S 23 on SW, S 14 on NW faces, also 3 notches on S & 1 notch on the E edges; from which

A cedar, 10" dia., bears N.18°E., 26 lks., mkd: T31S R9W S13 BT.
A cedar, 12" dia., bears S.30°E., 10 lks., mkd: T31S R9W S24 BT.
A cedar, 12" dia., bears S.38°W., 39 lks., mkd: T31S R9W S23 BT.
A fir, 8" dia. bears N.72°W., 13 lks. mkd: T31S R9W S14 BT

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & C. Stone - Feb. & March 1967 - C.S. File 54/32-13

Found - Unrecorded 1" Iron Pipe at section corner.
Orig. 12", now 15",. S.30°E., 6.6 ft. scribe marks visible, but not legible.
Orig. Cedar, now dead, N.18°E., 17.2 ft. scribe visible.
No trace of S.W. nor N.W. BT's.

Unrecorded Trees -
8" W.Fir N.84°W., 61.1 ft., scribe marks visible.
10" Cedar S.45°W. 41.4 ft. scribe visible.

Set Brass Cap at Cor. mkd: County Surveyors T31S R9W
(alongside IP) Office S 14 | S 23
1967 S 23 | S 21

New BT - 12" D.Fir N.15°E., 69.3. ft. mkd. T31S R9W CS BT.

Tony Hostetter - For: Roseburg Resources Co. & Plum Creek - Sept. 2009 - M160-4

Found - 1967 Brass cap and accessories described by Douglas Co. Surveyor (C.S. file 54/32) EXCEPT
12" Cedar OBT now 26" bears S.16°E. (Not S.30°E) 6.6'
10" Cedar @ S.45°W., now 26"

Corey Woodruff - For: Plum Cr. Timberlands - 7/2010 - M161-7

Found - 1967 Douglas County Surveyor BC/IP
21" W.Fir brs. N.84°W., 61.5'
26" P.O. Cedar brs. S.45°W., 42.0'
15" P.O. Cedar brs. S.17°E., 6.9'
12" D.Fir stump brs. N.15°E., 68.9'