

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs. 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #727, dated December 20, 1900 - (DCSO records Vol. 19 Page(s) 8188)

Set a cedar post, 4 ft. long, 4" sq. 24" in the ground, marked T31S S1 on NE, R9W S12 on SE, S11 on SW, and S2 on the NW faces for the corner of Secs. 1, 2, 11, & 12 from which
A cedar, 24" dia., bears N.50°E., 35 lks., mkd: T31S R9W S1 BT.
A fir, 16" dia. bears S.71°E. 79 lks. mkd: T31S R9W S12 BT
A fir, 36" dia. bears S.63°W. 60 lks. mkd: T31S R9W S11 BT
A fir, 36" dia. bears N.70°W., 18 lks. mkd: T31S R9W S2 BT

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & E. West - Feb. 1967 - C.S. File 54/32-90

Found - Orig. 24", now 29" Cedar, N.50°E., 23.1 ft., opened for scribe "R9".
Orig. 36", now 37" Fir, N.70°W. 11.9 ft., shows good scar.
Orig. 36", now 42" Fir, S.57°W. 39.6 ft., shows good scar. (Record bearing S.63°W.)
Set - Brass Cap at Cor. mkd: County Surveyors T31S R9W
Office S 2 | S 1
1967 S 11 | S 12
New BT - 8" W. Fir S.26°E. 87.4 ft. mkd. T31S R9W S12 CS BT

Fd. BC & BTs by R. Brandt, 7/1971 - C.S. File 55/191-2