

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 456 dated July 28, 1882 (DCSO records Vol. 19 Page(s) 8106)

Set a Cedar post 3 ft. long, 3" sq., 20" in the ground, mkd. 1/4 S on the W. side for the 1/4 sec. cor., and from which
A Fir 24" dia., bears N.64°E., 18 lks. dist. mkd. 1/4 S BT
A Fir 22" dia., bears S.43°W., 14 lks. dist. mkd. 1/4 S BT

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8241)

Corner post gone. Set a Fir post, 4 ft. long, 4" sq., 24" in the ground, mkd. 1/4 S on E. and S13 1/4 S on W. faces. Established from old witness corners.

BLM Resurvey by C.A. White, H.D. Corbing Cad. Surveyor & D.R. Beck, Surveying Tech, Under Group #446, Surveyed Nov. 1960/Sept. 1962 - (DCSO recs Vol. 31 Pages 13185-86)

The 1/4 sec cor. determined at record distance from the OBTs:
A Fir 37" dia., bears N.53 3/4°E., 18 lks. dist., mkd. 1/4 S BT on bark blaze, remarked 1/4 S18 BT on bark blaze. (Rec. brg. N.64°E.)
A Fir 31" dia., bears S.48 3/4°W., 14 lks. dist., visible scribe marks on bark blaze, remarked 1/4 S13 BT. (Rec. brg. S.43°W.)

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

1/4
S 13 | S 18
R 9 W | R 8 W
T 31 S
1962

Douglas Co. Surveyors Office - John M. Powell, and crew - March 17, 1967 - C.S. File 54/32-43

Found - GLO brass cap mkd. in 1962.
37" D.Fir, now broken snag, N.53 3/4°E., 11.9 ft., bark scribed 1/4 S18 BT.
31" D.Fir, now stump, S.48 3/4°W., 9.2 ft. Stump out of ground, scribe visible S13.
New BTs- 14" D.Fir N.77°E., 18.8 ft. mkd. 1/4 S18 CS BT.
6" Live Oak S.14°W., 56.6 ft. mkd. 1/4 S13 CS BT.
Corner lies East of Elk Valley Road approx. 150 ft.

Fd. BC & BTs by C. Woodruff, 4/2008 - M156-5
Fd. by C. Woodruff, 6/2010 - M161-7 continued next page

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & 18, T31-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ron Quimby - Crew: N. Fromdahl & R. Olsen - 2/2015 - C.S.
File 65/87-14

Found - BLM brass cap
35" Fir snag, N.50°E., 12.0 ft. (rotted)
26" Fir N.77°E., 18.8 ft. good scar.
New - 12" Fir N.35°W., 15.8 ft. scribed ¼ S13 BT.
6" Fir S.36°W., 24.5 ft. scribed ¼ S13 BT.
16" Fir S.15°W., 37.2 ft. scribed ¼ S13 BT.
Clear cut unit to the east.
Note - Corner is on west of new clear cut unit approx 200'
east of Rd. #31-8-31 and approx. 200' north of
logging spur to clear cut. Rd. #9-13

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 2-10-25 - C.S. File 67/60-4

Found - BLM brass cap projecting 4"
30"x10ft very rotted fir snag N.50°E. 12.0ft. No
blaze, no nail.
26"x11ft sawn fir N.77°E. 18.8ft. Fully healed
single blaze.
17" Fir N.35°W. 15.9ft (rec 15.8ft) fully healed
single blaze.
10" Fir S.36°W. 24.3ft (rec 24.5ft) fully healed
single blaze.
23" Fir S.15°W. 37.2ft fully healed single blaze.
Metal posts 1½ft south and on north edge of B.C.
All trees were side spiked with 3½" mag nails
right side center.

Notes - Mon is approx 200' E. of gravel road on moderate
W., slope. Young reprod to E., older forest W.

Compass decl. 14½°E.
O CRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N 42.87508 W 123.70199