

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20 & 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Rufus S. Moore, Deputy Surveyor, under contract 475 dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8268)

A point about 400 ft. above $\frac{1}{4}$ sec. cor. and Set a fir post, 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 16, 17, 20, & 21, marked T32S S 16 on NE, R1W S 21 on SE, S 20 on SW, and S 17 on NW faces, with 3 notches on S & 4 notches on E edges; from which

A fir, 8" dia. bears N.56°E., 59 lks. mkd: T32S R1W S16 BT
A fir, 8" dia. bears S.68°E., 23 lks. mkd: T32S R1W S21 BT
A fir, 4" dia. bears S.55°W., 20 lks. mkd: T32S R1W S20 BT
A fir, 16" dia. bears N.48°W., 28 lks mkd: T32S R1W S17 BT

Douglas Co. Surveyors Office - Frank Jones - W. Penley - 7/31/1968 - C.S. File 54/71-14

Reported as not found.

Found line crossing 792' north of corner & good north, south blazed line W/east-west ribbon line, but no trace of corner.

Burton W. Holt - For: Sun Studs - Aug. 1974 - M49-71

Set - Brass cap

New - 13" D.Fir, bears S.50°30'W., 18.5 ft. scribed T32S R1W S20 BT.

35" D.Fir, bears S.20°E., 13.7 ft., scribed T32S R1W S21 BT.

42" D.Fir, bears N.16°E., 27.1 ft., bark scribed T32S R1W S16 BT.

6" I.Cedar bears N.48°W., 15.3 ft., scribed S17 BT.

Burton W. Holt - For: Sun Studs - Revised from survey in 1974, M49-71 Revised June 20, 1979 - M70-72

Set - Brass cap

New - 15" D.Fir bears S.72°W. 44.0 ft scribed T32S R1W S20 BT

6" W.Fir bears S.53°E., 30.9 ft scribed T32S R1W S21 BT

8" D.Fir bears N.19°E., 9.9 ft. scribed T32S R1W S16 BT

7" Cedar bears N.79°W., 38.4 ft. scribed S17 BT.

This is a revision of 1974 renewal **See C.S. File 63/166 for 1998 BLM opinion.**

Mark Smalley - For: R F P - 10/4/2002 - C.S. 65/44-19

Found - Iron pipe brass cap & National Forest post/sign.

10" Fir snag N.19°E., 9.9 (15' tall) healed face

8" Cedar snag N.79°W. 38.4 (8' tall) scribe vis.

15" Fir rootwad S.72°W., 44.0 continued next pg

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20 & 21

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

New - 6" Fir S.53°E., 30.9 gone - in clear cut.
 15" S.30°E., 10.7 scribed "S21 BT"
 13" Fir N.69°E., 19.6 scribed "S16 BT"
 6" Fir N.10°W., 20.1 scribed "S17 BT"
 2½" fir S.16°W., no scribe - tag only.

Leonard Herzstein - USFS - 8/8/2005 - C.S. File 65/54-35

Burton W. Holt reestablished this corner in 1974 by double proportioning. Holt corrected his 1974 reestablishment in 1979. His 1974 survey had measurement errors. He reset a brass cap and marked BTs. Mark F. Smalley, renewed this corner in 2002 He marked new BTs. The Jackson County Surveyor's Office recovered the original ¼ corner of sections 20 and 21, in 1984 (Jackson County first re-establishment). This original corner is closer to the section corner than the double proportioning control used by Holt in 1979. Ken W. Hoffine, L.S. 2291, received an opinion from BLM in 1998, that if the 1979 proportioned corner position was within a few feet of are-proportioning of the corner, BLM would accept the 1979 position (C.S. File No. 63/166 [T32S, R1W], Douglas County). Surveyor Hoffine found the 1979 monument to be 3.6 feet from a re-proportioned position based on the original ¼ corner of sections 20 and 21 and he accepted the 1979 monument. I therefore accept Holt's 1979 sec. corner monument as the location for the section corner.

Found - 3" dia iron pipe, firmly set, projecting 6" above ground, with a 3" dia brass cap attached, (Properly) mkd.

10" D.Fir snag, bears N.12°E. 9.9 ft (rec N.19°E.), with a healed blaze. 1979

A roothole bears S.72°W., 44.0 ft, with 16" D.Fir alongside with no marks visible. 1979

8" I.Cedar snag, bears N.84°W., 38.4 ft (rec. N.79°W.), with scribe marks "S 17 BT" visible on a partially healed blaze. 1979

16" D.Fir cut stump, bears N.64½°E., 19.6 ft (rec. N.69°E.), with no marks visible. 2002

14" white fir, bears S.33°E. 10.7 ft (rec. S.30°E.) with scribe marks "S21 BT" & a ¾" dia. brass washer, stamped "LS 2354", visible on a partially healed single blaze.

4" D.Fir, bears S.12°W., 14.9 ft (rec. S.16°W.), with Roseburg Resources tag.

8" D.Fir, bears N.10°W., 20.1 ft, with scribe marks "S17 BT" and a 3/4" diameter brass washer, stamped "LS 2354", visible on a partially healed single blaze. cont. next page

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20 & 21

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

New - I add a mound of stone. The monument is now projecting 4" above a 2 ft dia mound of stone.
I added new accessories to perpetuate the corner:
A fd steel fence post projecting 4 ft above ground, bears N.2¾°E., 3.1 feet, with Forest Service signs #54-4 "Attention" and #54-2 "Property Boundary" signs attached.
An 11" incense cedar, bears S.70¼°W., 71.7 ft, with scribed "T32S R1W S20 BT" and a 3/4" dia brass washer, stamped "LS 2150", nailed flush to a single blaze.
No trees are available in a recent clear cut in section 16. With a 1-second total station, I traversed the section line to the ¼ corner of sections 17 and 20 and I used the platted bearing of S.85°34'19"E. (M70-72) as my basis of bearings. Bearings for this renewal are rounded to the nearest 15 minutes. With a staff compass at the corner point, I determined the magnetic decl to be 17° East. Trees are measured to the center of the root crown. Tree diameters are at breast height.