

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T31-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7461)

Set ¼ sec. post, from which
A Fir 30" dia. bears N.30°W., 14 lks. dist.
A Cedar 36" dia. bears S.15°W., 52 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7488)

The old ¼ sec. cor. on S. bdy. of sec. 33, which is a decayed post, with 1 BT still standing. I destroyed this post and replaced it with a basalt stone 14x10x8 ins. 10" in the ground mkd. ¼ on N. face, from which
A Cedar 40" dia., bears S.15°W., 52 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears N.3°E., 29 lks. dist. mkd. ¼ S BT.
The Cedar is the one described in field notes of original survey and was newly marked.

Douglas Co. Surveyors Office - John M. Powell, and crew - July/Aug. 1968 - C.S. File 54/71-21

Found - 14x10x8 corner stone mkd. with "¼" on the N. face. 40" now 46" Cedar S.25°W., 39.0 ft. (Rec. S.15°W., 34.3 ft.) shows scribing.
36" Fir now 38" stump, N.3°E., 19.1 ft., opened and found scribing "¼ BT"

Set Brass cap at cor. mkd: County Surveyors Office
T31S R1W ¼ S 33
T32S 1968

New BTs- 14" Cedar N.54°W., 41.0 ft. mkd. ¼ S33 CS BT.
12" Fir N.42°E., 46.6 ft. mkd. ¼ S33 CS BT.

Cor. lies in S-W fence corner 150.1 ft. East of the sec. cor. to 4 & 5, T32-1W. and 300 ft. North of a road.

Fd. OK, Dec. 1992 by Kaiser - M 116-30

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Jeff Lorsung - 6/4/2019 (filed 1/28/2021) - C.S. File 67/48-21

Found - A 1" I.D. iron pipe, firmly set, projecting 15" above the ground in a rough mound of stone with a 2½" dia. brass cap (properly) marked
An orig BT by D Hathorn, USGLO Deputy Surveyor, in 1857:
A 48" dia. I.Cedar is uprooted and tipped out of the roothole which bears S.25°W., 34.3 ft. (Rec. S.15°W., 52 lks.) Continued next page

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 302700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T31-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A BT by R Moore, USGLO Deputy Surveyor in 1883:
A 30" dia.x3' tall rotted D.Fir stump bears N.3°E.,
19.1 ft with no evidence of blaze remaining
BTs by J. Powell, Douglas Co Surveyors Office in 1968:
A 22" dia. D.Fir bears N.31°E., 46.6 ft, with a
fully healed blaze. (Rec. N.42°E.)
A 33" dia double trunk I.Cedar bears N.58½°W., 41 5
ft with a fully healed blaze on SE trunk. (Rec.
N.54°W. 41.0 ft)
New BO - The brass cap monument for the corner of Sections 4
& 5 only of T32S R1W bears West, 150.8 ft.
Note - Compass declination 14¼°E.
The corner falls on the edge of mixed timber cut line
with fences running North and West and is located
approximately 300 ft north of an access road
All BTs have BT Tags attached. All new BTs have
double blazed faces with bearing measured to the
center of the tree at the root crown and
distances measured to a 4" mag spike in the side
and center of the root crown.
Geodetic coordinates
Latitude: 42°49'43.33"N. Longitude: 122°50'00.12"W.
DATUM: NAD 83 SOURCE: GeoXT6000