

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 402700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 34 only, T31-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7462)

Set 1/4 sec. post and built stone mound, from which
A Laurel 9" dia., bears S.20°E., 17 lks. dist.
A Fir 18" dia., bears N.70°E., 30 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7486-87)

(A point on line where the old ¼ sec. cor. on S. bdy. of sec. 34, bears South, 193 lks. dist.)
The old ¼ sec. cor. on S. bdy. of sec. 34, which is a post greatly decayed with 2 BTs still standing. As T31S R1W has been subdivided, I could not change the location of this cor. I, therefore, destroyed the old post and replaced it with a basalt stone, 14x8x8 ins., 10" in the ground, mkd. ¼ on N. face, from which
A Laurel 9" dia., bears S.20°E., 17 lks. dist. mkd. ¼ S BT.
A Fir 30" dia., bears N.70°E., 30 lks. dist. mkd. ¼ S BT.
The BTs are those described in field notes of the original survey and were newly marked. Could find no traces of stone mound described in old field notes.

Douglas Co. Surveyors Office - John M. Powell, and crew - July/Aug. 1968 - C.S. File 54/71-25

Found - No trace of stone or SE. BT.
30" now 30" D.Fir N.70°E., 19.8 ft., opened for scribe "4 S".
Set Brass cap at cor. mkd: County Surveyors Office
T 31 S R 1 W
¼ S 34
T 32 S
1968
New BT - 13" D.Fir N.42°W., 20.6 ft. mkd. ¼ S34 CS BT.
NE. BT OK and tagged.