

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35 only, T31-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 18 Page(s) 7462)

Set post cor. secs. 34, 35, 2 and 3, from which
A Fir 15" dia., bears S.12°E., 55 lks. dist.
A Fir 15" dia., bears S.70°W., 32 lks. dist.
A Fir 18" dia., bears N.38°E., 19 lks. dist.
A Fir 12" dia., bears N.2°W., 113 lks. dist.

GLO Survey by Rufus S. Moore, Deputy Surveyor, under Contract #475, dated July 3, 1883 - (DCSO records Vol. 18 Page(s) 7485-86)

The old cor. to secs. 34 and 35, at a point about 150 ft. above creek, which is a post 4" sq., rotten and decayed but still standing, with marks almost obliterated, from which I find two bearing trees:

A Fir 20" dia., bears S.70°W., 32 lks. dist. mkd. T32S R1W S3 BT.

A Fir 24" dia., bears S.12°E., 55 lks. T32S R1W S2 BT.

I destroy the marks on the BT and also the old post, and replace it with a basalt stone, 15x10x5 ins., 10" in the ground for cor. to secs. 34 and 35, mkd. with 2 notches on E. and 4 notches on W. edges, from which

I take two additional bearing trees:

A Maple 6" dia., bears N.64°E., 52 lks. dist. mkd. T31S R1W S35 BT.

A Maple 6" dia., bears N.34°W., 40 lks. dist. mkd. T31S R1W S34 BT.

GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Special Instructions, dated June 7, 1922 - (DCSO records Vol. 18 Page(s) 7517)

The sec. cor., which is a basalt stone firmly set, 5x10x5 ins. above ground, marked with 2 notches on E. and 4 notches on W. edges; from which

A Maple 6" dia., bears N.64°E., 52 lks. dist. mkd. T31S R1W S35 BT. (Old BT)

A Fir 20" dia., bears S.70°W., 32 lks. dist. mkd. T32S R1W S3 BT. (Old BT)

A Maple 6" dia., bears N.34°W., 40 lks. dist. mkd. T31S R1W S34 BT (Old BT)

I obliterate the marks on the bearing tree referring to sec. 3, T32S R1W and remark the stone, S34 on NW. and S35 on NE. face.

(Cont. Next Page)

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 443700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35 only, T31-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Arthur Boyer, Surveyor - Wit: Ted Schattenkerk - Sept. 1949 -
C.S. File 40/214

Found two orig. BTs for this cor., the two Maples, the one to the NE. still alive and standing and the one to the NW. still standing but showing signs of decay; found also the tree to the SE., a Fir snag and found the stump of the BT to the SW. This cor. applies to secs. 34-35, so marked a new tree to the NW. only.

12" Maple N.46°30'W., 16½ ft. scribed S34 1581 BT.

At corner, raised a mound of rocks 12" high and a 4" x 4" Cedar post.

Corner is in a shallow rocky draw which drains into a creek approx. 600 ft. N. Cor. is 80 ft. S. of old phone line.

Douglas Co. Surveyors Office - John M. Powell, and crew -
Aug. 1968 - C.S. File 54/71-44

Found - Mound of stone at corner.

12" now (?) Maple N.46½°W., 16.5 ft., scribe visible
"34 BT"

6" now 10" Maple N.64°E., 34.6 ft., rotten face,
"BT" visible.

6" now 6" Maple, opened and rotten, N.34°W., 26.4 ft
SW. BT, 20" Fir, not found.

Set Brass cap at cor. mkd: County Surveyors Office

T 31 S R 1 W

S 34 | S 35

S 3

T 32 S

1968

Reblazed and rescribed:

10" Maple N.64°E., 34.6 ft. mkd. T31S R1W S35 CS BT

New BT - 24" D.Fir S.79°W., 36.5 ft. mkd. T32S R1W S3 CS BT.