

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Rufus S. Moore, Deputy Surveyor, under contract 475 dated July 3, 1883 - (DCSO records Vol. 19 Page(s) 8257)

-----

Set a basalt stone 18x14x12", 12" in the ground for cor. of secs. 2, 3, 10, & 11 about 250 ft. below top of last ridge, mkd with 5 notches on S & 2 notches on E edges, from which

A fir, 45" dia. bears N.68°E., 58 lks. mkd: T32S R1W S2 BT  
A fir, 35" dia. bears S.60°E. 12 lks. mkd: T32S R1W S11 BT  
A fir, 54" dia. bears S.75°W. 17 lks. mkd: T32S R1W S10 BT  
A fir, 44" dia. bears N.50°W., 35 lks. mkd: T32S R1W S3 BT

BLM Dependent resurvey by Hans W Thielsen, under Group #318, surveyed Aug/Sept 1955 - (DCSO records Vol. 28 Page(s) 12132)

-----

The cor. of secs. 2, 3, 10, & 11, determined at record bearing & distance from the orig. BTs:

A fir, 45" dia., bears N.68°E., 58 lks., marked with ah healed blaze.  
A fir stump, 35" dia., bears S.60°E., 12 lks., with no remaining marks.  
A fir, 50" dia., bears S.75°W., 17 lks., marked with a healed blaze.  
A fir, 44" dia., bears N.50°W., 35 lks., with marks S3 un-covered.

At the corner point  
Set an iron post, 36" long, 2" dia., 30" in the ground, with brass cap marked:

T32S	R1W
<u>S 3</u>	<u>S 2</u>
S 10	S 11
1955	

from which new BTs

A fir, 37" dia. bears N.89°E., 106 lks mkd: T32S R1W S2 BT  
A fir, 37" dia. bears S.36°E., 77 lks mkd: T32S R1W S11 BT  
A fir, 40" dia., bears S.32½°W., 377 lks., mkd: T32S R1W S10 BT.  
A fir, 23" dia., bears N.73¼°W., 127 lks., mkd: T32S R1W S3 BT.

Gerald Nygren - For: USFS - July 1989 - C.S. 63/85-30

-----

Found - 1½" iron pipe with 1955 GLO 2½" brass cap.  
48" fir snag, N.70°E., 34.8 ft. (healed blaze) Rec. N.68°E., 58 lks.  
36" fir, S.79°E., 67.8 ft. (healed blaze) Rec. N.89°E., 106 lks.  
63" fir stump, S.75°W., 11.2 ft (healed blaze) Orig.  
30" fir, N.65°W., 82.5 ft. (healed blaze) Rec. N.73¼°W., 127 lks. continued next page

TOWNSHIP 32 RANGE 01 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Cor. Secs. 2, 3, 10, & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

46" fir N.50°W., 22.6 ft. (healed blaze) Orig.  
Note - Above monument (iron pipe) is badly bent.  
New BT - A 7" fir S.46°W., 6.0 ft. scribed "T32S R1W S10 BT"  
Nailed ½" dia., brass washer "LS 1035" to lower  
blaze.

Gerald V. Nygren, PLS #1035 - For: United States Department  
of Agriculture, Umpqua National Forest - July 1991 thru Sept.  
1993 - M 118-20 - C.S. File 63/134 (N)

-----  
Found - 2½" iron pipe (bent) w/brass cap (properly) stamped.  
Note - Iron pipe is bent Northerly, the following bearings  
& distances were measured from that portion of  
pipe which is vertical & below bend.  
Found - D.Fir snag, 48" dia., bears N.70°E., 34.8', healed  
blaze.  
D.Fir stump, 63" dia., bears S.75°W., 11.2', healed  
blaze.  
D.Fir, 36" dia., bears S.89°E., 67.0', healed blaze.  
D.Fir, 30" dia., bears N.65°W., 82.5', healed blaze.  
D.Fir, 46" dia., bears N.50°W., 22.6', healed blaze.  
D.Fir, 10" dia., bears S.46°W., 6.0', visible  
scribe.  
New BT- D.Fir, 6" dia., bears N.6°E., 8.9' scribed "T32S R1W  
S2 BT"