

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 30 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747,, dated May 5,1902 - (DCSO records Vol. 19 Page(s) 8287)

Set a granite stone 18x12x12 ins., 12" in ground for ¼ sec. cor. marked ¼ on the West face, from which
A Matherone 10" dia., bears N.10°E., 45 lks. mkd. ¼ S30 BT
A Fir 38" dia., bears S.17°W., 76 lks. dist. mkd. ¼ S25 BT

GLO survey by Fred Mensch, U.S. Surveyor, Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8356)

Intersect the old ¼ cor. of secs. 25 and 30 which is a stone, firmly set, mkd. and witnessed as described by the surveyor general. I now change this cor. to refer to sec. 30 only, as follows:
I destroy the marks on W. and mark ¼ on E. face of stone, for ¼ cor. of sec. 30, T32S R2W only, from which
A Madrona 10" dia., bears N.1°30'E., 45 lks. dist.mkd. ¼ S30 BT.
A Yew 12" dia., bears S.5°30'E., 107 lks. dist. mkd. ¼ S30 BT.
I destroy the marks on former bearing tree in sec. 25.

Survey by William Ruppert - For: U.S. Forest Service - May 1980 - M 84-6 and C.S. File 58/143 (n)

Found - Orig. 12" x 12" x 12" stone, loosely set and broken in two, no marks.
16" Madrone N.3°06'E., 27.3 ft., hollow.
50" snag, S.15°36'W., 47.9 ft., good scar.
Set 2" x 30" galv. Iron pipe with 2½" brass cap mkd. "T32S R2W ¼ S30 PLS 866 1980", at location of stone.
New BTs- 6" Chinquapin, S.47°04'E., 31.3 ft. scribed "¼ S30 BT".
7" D.Fir N.14°46'E., 70.7 ft.scribed "¼ S30 BT"
Attached 3/4" brass washer mkd. "LS 866" to lower blaze of each new BT.

Edward McGinty, Jackson County Surveyor with R. Frost and S. Beecher, techs. - Nov. 3, 1988 - C.S. File 63/82

Found - Projecting 10" in ring of stone, the 2" dia. galv. I.P. with 2½" dia., brass cap set by Ruppert.
(Cont. Next Page)

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 30 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An orig. BT mkd. by Campbell in 1902, now a sawed Madrone stump 18" dia. containing partial scribed "3" and "BT" in rotted face, bears N.3°E., 27.41 ft. to center of stump. (Rec. N.1½°E., 29.70 ft.)

An orig. BT, subsequently relegated to a "former bearing tree" on a 1913 resurvey, now a burnt Fir snag, 48" dia., containing old axe work, bears S.15½°W., 47.63 ft. to center of tree. (Rec.S.17°W., 50.16 ft.)

The orig. stone could not be found, nor the Yew BT reported in 1913.

As all trees in the vicinity of the corner have been destroyed by recent (1987) forest fire; Set references as follows:

- 5/8" x 24" rebar set 22" in the ground with yellow plastic cap mkd. "Jackson C.S.", bears N.66°E., 8.19 ft.
- 5/8" x 24" rebar set 22" in he ground with yellow plastic cap mkd. "Jackson C.S.", bears S.50°E., 6.45 ft. located at the base of 48" dia. Fir stump.

Corner lies on steep (65%) SW. slope, about 225 ft. SW. of road.