

TOWNSHIP 32 RANGE 02 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8335

Set an ironstone 24x10x8", 18" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which

A fir, 40" dia., bears N.31½°E., 25 lks., mkd: ¼ S4 BT.

A fir, 24" dia., bears S.89°W., 45 lks., mkd: ¼ S9 BT.

Douglas Co. Surveyors Office - A. Vic. Cangie - Clell Goodwin - Gary Langlitz - Lenora Ladig - 2/12/1976 - C.S. 59/2-17

Found - Ironstone 24"x10"x8" firmly in ground with "¼" marked on North face, and orig. BTs

A fir stump was 24" now 32" that bears S.89°W., and 29.7. Blaze was open on arrival and there were visible scribe marks(BT) on face

A 40" now 44" fir tree with good scar bears N.39°E., and 16.5 ft (record N.31½°E.) Tree is alive and in good condition.

At the corner point we set a 1"x30" IP with brass cap attached. We also set orig. stone on North side of Brass cap with "¼" mark, facing north as per orig. notes. Brass cap reads T32S R2W

DOUGLAS COUNTY SURVEYOR
1976

$\frac{S\ 4}{S\ 9}$ ¼

New BTs- 13" madrone scribed "¼" S9 CSBT" in a double blaze bears S.50°W., and 33.7 distance.

20°E Compass Declination.