

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias	Description

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8310

-----

Set an ironstone 24x12x8", 18" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which

- A fir, 36" dia., bears N.52°E., 46 lks., mkd: ¼ S14 BT.
- A fir, 24" dia., bears S.60½°W., 17 lks., mkd: ¼ S15 BT.

-----

Douglas Co. Surveyors Office - W. Penley & J.H. - 6/15/1970 (typed 3/1/2011)- C.S. File 54/117-3

-----

Found - 48" Fir N.53°E., 30.4 shows good scar.  
30" Fir snag S.60½°W., 11.2 shows good scar.  
Stone 24x12x8 ¼ on W face.  
No BT in SW limits

Set - Brass cap at cor. mkd: T32S R2W  
¼ S15|S14  
1970

-----

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Vincent Perron - 7/24/1970 - C.S. File 54/117-4

-----

Found - 1970 CS Brass Cap mkd: County Surveyors T32S R2W  
Office 1970 ¼ S15|S14  
(This Brass Cap mkd. by W. Penley, see notes in C.S. File 54/117, typed 3/1/2011)

Old Corner Stone mkd: "¼" alongside Brass Cap.  
Orig. 36", now 4.8" Fir, alive, N.52°E. 30.4 ft., shows good scar.  
Orig. 24" Fir, now 30" Snag, S.60½°W. 11.2 ft., shows good scar.

New BTs- 8" W.Fir N.14°W. 46.0 ft. mkd: "¼ S15 CS BT".  
24" W.Fir S.23°W. 67.6 ft. mkd: "¼" S15 CS BT".  
15" W.Fir S.20°E. 30.3 ft. mkd: "¼" S14 CS BT".

This corner lies approx. 200 ft. north of logging road, course SE & NW.