

PRIMARY CORNER DESCRIPTION (W.C.) 1/4 Cor. Secs. 11 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747 dated May 5, 1902 - (DCSO records Vol. 20 Page(s) 8301

A yew, 18" dia., for ¼ sec. cor., marked ¼ S11 on W and S12 on E., faces, from which

A fir, 28" dia., bears N.81°W., 56 lks., mkd: ¼ S BT.

A fir, 26" dia., bears S.60°E., 30 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Gary L. Langlitz - A. Vic Cangie - Debbie L. Stewart - 6/29/1976 - C.S. File 59/15-23

Found - The orig. corner monument, an 18" Yew tree, now a 10" snag, firmly in place at the corner point, with scribing "¼ S12" visible on the unhealed East face. The west face has been burnt out, no marks remaining.

A 26" Fir, now 36" D.Fir stump, well-healed.

The orig. NW bearing tree is gone.

We leave the orig. corner tree intact and mark the following new BT:

A 24" D.Fir bears S.2°W., 51.7 ft. scribed "¼ S11 CS BT on a double blaze.

An 11" Hemlock bears S.57°W., 68.1 ft. scribed "¼ S11 CS BT" on a double blaze.

At a point which bears South 4.0 ft. from the true corner, we set a reference monument as follows:

A 1"x30" IP " in the ground, w/brass cap attached	
Mkd: Douglas Co. Surveyor	Reference Monument
1976	↑

North 4.0 feet
S 11 S 12
T32S R2W