

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 13

Alias	Description

Glenn S. Baughman - For: USFS - Dec. 1976 - M56-69; M56-70; M56-68

-----  
Set - 2"x30" IP with brass cap stamped T32S R2W C¼ S13 OLS 536 1976  
New - 10" fir bears S.9°W., 43.4 ft. scribed C¼ S13 BT with brass washer stamped LS 536.  
12" fir bears N.17°E., 11.4 ft. scribed C¼ S13 BT with brass washer stamped LS 536.  
Corner falls 15 ft South of small creek.

John Ransom, USFS - Jonathan Drew - 12/2013 - C.S. 65/85-36

-----  
Found - 3" brass cap (properly mkd) on 2¾" iron pipe, projecting 3" above a small mound of stone  
26" Fir stump N.20°30'E., 11.3 ft sawn stump, healed double blaze measure to mag nail flush in top  
27" Fir S.9°W., 43.8 ft healed double blaze  
New - A 32" Fir double tree bears, S.18°15'E., 41.8 ft. scribed "C¼S13" "BT" on a double blaze  
A 7" fir bears, S.46°W., - 27.5 ft, scribed "X" "BT" on a double blaze.  
BTs include ¾" brass washer marked "LS2561" between B & T on lower blaze  
Red paint applied to BT faces and a 6" band at head height, BTs include BT & survey monument tags  
Brush cleared around monument and to BTs  
"LAND LINE" flagging tied on monument & guard posts  
Measurements to accessories made with LEICA 1103+ TOTAL STATION with reflectorless EDM to aluminum nail set at side center, basis of bearing being plat record bearing (N.00°02'56"W.) (M56-68) using steel line post found about 103 feet north of corner.  
Note - Corner falls approx 80 feet north from centerline of a graveled road (FS RD 1616-140) take FS RD 1616 To gate, get key from Hancock Timber Management Company in Medford. Take road to timber corner, S.9°W. BT is visible from road, corner falls in a vine maple patch in a swampy area.  
Maintained line .5 miles north of corner.