

PRIMARY CORNER DESCRIPTION Cor. No. 3 Yellow King #1; MS 792

Alias _____ Description Cor. No. 2 Yellow King #2; MS 792
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Mineral Survey No. 792 by C. Frank Rhodes, US Mineral Surveyor under instructions dated July 25, 1916 - (DCSO Recs. Vol. 28 Page(s) 11905)

Cor. No. 3, identical with Cor. No. 1 Van Ostrand lode unsurveyed, Umpqua Copper Company claimant and with Cor. No. 3 of amended location.
A fir post, 5 ft. long, 6" sq., set 2 ft. in the ground scribed Y K No. 1-3 Y K No. 2-2-792; whence
 A fir, 22" dia., bears N.21°23'W., 18.12 ft. and
 A fir, 36" dia., bears S.74°16'W., 32.10 ft., each blazed and scribed BT Y K No. 1-3 Y K No. 2-2-792

Douglas Co. Surveyors Office - R.B. Kimberling - P.L. Earle - April 3, 1978 - C.S. file 59/46-26

Found - A rotted Fir post, 2 ft. long, 6" sq. with scribing on one side. I dig and find rotted wood in a 6" sq hole, 2 ft. deep. I use as corner.
 A 22" now 30" Fir snag, 30 ft. high, bears N.21½°W., 18.8 ft. is good to orig. face with a well healed single blaze.
 A 36" now 48" Fir stump bears S.74½°W., 33.2 ft. (Rec. 32.1 ft. is good to orig. face), with a well healed single blaze.
Set - A 1"x36" IP w/ brass cap set 2" above ground & mkd:
" Douglas County Surveyor"
 \\ YK No.
 \\ 2-2
 // YK No.
 // 1-3
New BTs- A 7" D.Fir bears N.2½°E., 15.1 ft. with a crooked trunk. I drive a nail in a notch at the center of the crown, double blaze and scribe "YK No 1-3 YK No 2-2-792 CS BT".
 A 11" Hemlock bears S.83°W., 36.4 ft. I double blaze and scribe "YK No 1-3 YK No 2-2-792 CS BT".
Corner is at West edge of clearcut.