

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Sec. 24 only, T32-4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8378)

-----  
Set a basalt stone 14x8x8 ins., 9" in the ground for the 1/4 sec. cor., marked 1/4 S on W. face, from which  
A Cedar 14" dia., bears N.80°E., 36 lks. dist., mkd. 1/4 S BT.  
A Cedar 20" dia., bears S.55°W., 37 lks. dist., mkd. 1/4 S BT.  
This cor. is on a hillside, sloping SE. 25 ft. below top of spur.

GLO survey by Fred Mensch under special Instructions dated August 20, 1912 (DCSO records Vol. 20 Page(s) 8395)

-----  
The 1/4 sec. cor. of secs. 19 and 24 is a stone, firmly set, marked and witnessed as described by the Surveyor General. I now change this cor. to refer to Sec. 24 only, and re-witness as follows: From cor.  
A Cedar 20" dia., bears S.55°W., 37 lks. dist., mkd. 1/4 S24 BT.  
A Fir 10" dia., bears N.44°W., 44 lks. dist., mkd. 1/4 S24 BT.  
I destroy the marks on former bearing tree referring to Sec. 19.

GLO resurvey by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12773-74)

-----  
The 1/4 sec. cor. of sec. 24 only, monumented by Nicklin with a basalt stone, 14x8x8 ins., firmly set, marked 1/4 on W. face, from which the only remaining original bearing tree:  
A Cedar 30" dia., bears S.55°W., 37 lks. dist., mkd. 1/4 S24 BT on open blaze.  
At the corner point  
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked  
1/4 S 24  
R4W R3W  
T32S  
1959  
from which a new bearing tree  
A Fir 18" dia., bears N.42°W., 47 lks. dist., mkd. 1/4 S24 BT.  
Deposit basalt stone alongside iron post.