

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; and 13 of T32-4

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8376-77)

-----  
Set a Chinquapin post, 3½ ft. long, 4" sq., 24" in the ground for ¼ cor., marked ¼ S. on West face, from which

A Chinquapin 6" dia., bears N.60°E., 13 lks. dist., mkd. ¼ S BT.

A Fir 50" dia., bears West, 18 lks. dist. mkd. ¼ S BT.  
This cor. is on a hillside, sloping SE. about 50 ft. below spur.

GLO survey by Fred Mensch under special Instructions dated August 20, 1912 (DCSO records Vol. 20 Page(s) 8397)

-----  
Intersect the point for the ¼ sec. cor. located by reference to the West bearing tree; all other traces of the cor. have disappeared. I re-establish this cor. in its original position for sec. 13 and 18, as follows:

Set a slate stone 18x12x8 ins., 12" in the ground, for ¼ sec. cor. of secs. 13 and 18, marked ¼ on West face; from which

A Fir 10" dia., bears S.78°E., 42 lks. mkd. ¼ S18 BT.

A Fir 50" dia., bears West, 18 lks. mkd. ¼ S13 BT.

Survey by John Madding - For: Bate Plywood - Nov. 22, 1963 - C.S. File 51/270

-----  
Area of this corner was logged and original stone lost. I found both Fir bearing trees, which are now stumps, with faces grown over. I chopped out both faces and exposed original scribing.

Replaced original stone with Iron pipe.