

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Cor. Secs. 7, 8, 17, & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8372)

Set post, cor. to secs. 7, 8, 17, & 18, from which
A hemlock, 6" dia., bears N.60°E., 75 lks.
A fir, 30" dia., bears S.78°E., 60 lks.
A hemlock, 5" dia., bears S.42°W., 36 lks.
A pine, 12" dia., bears N.40°W., 188 lks.

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8412)

The cor. of secs. 7, 8, 17, & 18 is a badly decayed post, marked as described by the Surveyor General.
The NW BT is still standing; the other trees have been destroyed by fir. I destroy this cor. & reestablish it in the same place as follows:
Set a granite stone 18x10x8", 12" in the ground for cor. of secs. 7, 8, 17, & 18 mkd with 4 notches on South & 5 notches on East edges, from which
A fir, 10" dia., bears N.39°E., 57 lks mkd: T32S R3W S8 BT
A fir, 15" dia. bears S.35°E., 80 lks mkd: T32S R3W S17 BT
A fir, 8" dia., bears S.5°W., 48 lks. mkd: T32S R3W S18 BT
A S.Pine, 10" dia., bears N.45°W., 20 lks., mkd: T32S R3W S7 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - July 1969 - C.S. File 54/91-34

Found - 10", now 18" D.Fir, N.39°E. 37.6 ft., shows good scar.
15", now 28" D.Fir, S.35°E. 52.8 ft., shows good scar.
8", now 14" D.Fir, S. 5°W. 31.7 ft., scribe visible, "S18 BT".
10", now 26" Pine, N.45°W. 13.2 ft., shows good scar.
18x10x8" Stone, firmly set mkd. with 4 notches on S. & 5 on the East.

Set - Brass Cap at Cor. mkd: County Surveyors T32S R3W
Office S 7 | S 8
1969 S 18 | S 17

All Bearing Trees are Tagged and in good condition.

Fd. Ok by G. Lang, 7/1995 - M123-79