

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 20 Page(s) 8369)</p> <p>-----</p> <p>Set ¼ sec. post, from which A fir, 10" dia., bears N.20°W., 12 lks. A fir, 10" dia., bears S.10°E., 23 lks.</p>
<p>H.W. Lawrence - May 10/June 21, 1951 - C.S. File 40/343</p> <p>-----</p> <p>Difficult to recognize, stake gone & both BTs down. Drove a 4 ft. fir post squared to 4" at the top end, firmly into the ground at the point S.20°E., 7.92 ft. from the hole made by the down, scribed 10" fir, as given in the orig. survey notes, from which A fir 33" dia., bears S.50°W., 14.2 ft. mkd: ¼ S BT. A fir 26" dia., bears N.51°E., 6.1 ft. mkd: ¼ S BT.</p>
<p>Douglas Co. Surveyors Office - George J. Wenderoth, Deputy - Oct. 1955 - M41-10 & C.S. File 47/17</p> <p>-----</p> <p>Found - 30" Fir, N.47°30'E., 6.3 ft. 1951 36" Fir, S.53°45'W., 14.4 ft. Rescribed both trees. Set ¾" I. Pipe.</p>
<p>Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-71</p> <p>-----</p> <p>Found - No trace of I.Pipe at corner due to Cat trail, 1955. 30" D.Fir, now snag, N.47½°E. 6.3 ft., pitched over scribing visible. 36", now 38" D.Fir, S.54°W. 14.4 ft., shows good scar.</p> <p>Set - Brass Cap at Cor. mkd: County Surveyors T32S R3W Office 1969 ¼ $\frac{S}{S} \frac{4}{9}$</p> <p>New BT - 7" D.Fir N.24°E. 32.7 ft. mkd: "¼ S 4 CS BT".</p>
<p>Fd. Ok 10/1994 - M121-13</p>