

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33, & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO rec Vol 20 Pg 8418)

Set a granite stone 15x6x6", 10" in the ground for cor. of secs. 27, 28, 33, & 34 mkd with 1 notch on South & 3 notches on East edge, from which

A fir, 28" dia. bears N.83°E., 52 lks mkd: T32S R3W S27 BT

A fir, 40" dia. bears S.82°E., 47 lks mkd: T32S R3W S34 BT

A cedar, 30" dia., bears S.7°W., 102 lks., mkd: T32S R3W S33 BT.

A fir, 40" dia. bears N.82°W., 16 lks mkd: T32S R3W S28 BT

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-65

Found - Corner stone, 15x6x6, firmly set mkd: 1 notch S & 3 notches E.

Orig. 28", now 36" D.Fir N.83°E., 34.3 ft. shows good scar.

Orig. 40" now 48" D.Fir S.82°E., 31.0 ft. shows good scar.

Orig. 40" now 45" D.Fir N.82°W., 10.6 ft. shows good scar.

Orig. 30" now 40" cedar S.7°W., 67.3 ft. shows good scar.

Set brass cap at mkd: COUNTY SURVEYORS T32S R3W
OFFICE S 28|S 27
1969 S 33|S 34

All BTs OK & tagged, cor. about on top of rounded spur, running West.

Jackson Co. Surveyors Office - Edward McGinty, Co. Surveyor - R. Frost - S. Beecher, Techs - Oct. 5, 1988 - C.S. 63/82-3

Found - Corner monument is fd. disturbed, apparently struck by logging equipment or log in tow. Fd. the 1x36" flanged bottom pipe with attached brass cap set by Douglas Co. Surveyor. Said monument has been nearly removed from the ground and bent. It lies horizontal & partially buried alongside the (buried) orig. 13x7x4" granite stone, mkd. with cross on top and 1 & 3 grooves on adjacent sides.

From the following evidence, set a 1x36 ins, galvanized iron pipe, with 2½" dia. brass cap mkd: T32S R3W

28|27

33|34

CS

continued next page

1988

from which

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33, & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original BTs mkd. by Mensch in 1913 fd:
Sawed Fir stump, 36" dia., with healed lower blaze,
bears N.83°E., 32.0 ft. to center of stump.
Record; 34.32 ft.
Sawed Fir stump, 48" dia., bears S.82°E., 29.60 ft.
to center. Record; 31.02 ft.
Cedar, 42" dia., with healed blazes, bears S.6½°W.,
67.1 ft. to center of tree at upper blaze.
Record; S.7°W., 67.32 ft.
Sawed Fir stump, 50" dia. bears record; N.82°W.,
10.56 ft to center.
Mk new trees "CS" "BT" and take measurements to center of
trees at lower blaze:
Chinquapin, 7" dia., bears N.17°E., 22.40 ft.
Chinquapin, 7" dia., bears S.52°E., 11.90 ft.
D.Fir, 30" dia., bears N.47°W., 27.90 ft.
Corner lies near top of west sloping ridge, an estimated 225
ft. west of location marker on large fir stump, alongside
road curving southwest and northeast.