

PRIMARY CORNER DESCRIPTION CC Secs. 13 & 14

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 20 Page(s) 8386)  
-----  
Set a slate stone 15x12x8", 10" in the ground for cor. of secs. 13, 14, 23, & 24 mkd with 3 notches on S & 1 notch on E edge, from which  
    A Hemlock, 8" dia., bears N.68°E., 37 lks., mkd: T32S R3W S13 BT.  
    A W.Fir, 12" dia., bears S.10°E., 26 lks., mkd: T32S R3W S24 BT.  
    A Hemlock, 10" dia., bears S.82°W., 48 lks., mkd: T32S R3W S23 BT.  
    A R.Fir, 18" dia. bears N.18°W., 30 lks., mkd: T32S R3W S14 BT.

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug 20, 1912 - (DCSO recs Vol 20 Pg 8399)  
-----  
Intersect cor. of secs. 13, 14, 23, & 24, which is a stone, firmly set in the ground, marked & witnessed as described by te Surveyor General, and which I now change to refer to Secs. 13 & 14 only, and destroy the marks on the former BTs in Secs. 23 & 24.

J. H. Markham, Jr - For: M & B Logging Co. - Wit: H.C. Stokes - Sept. 9, 1959 - C.S. File 42/356-14  
-----  
Found - 14" fir stump, logged, bears N.18°W., 19.0 ft. OBT  
        I rescribed S14 BT.  
        12" W.Fir stump, logged bears S.10°E., 17.2 ft. OBT  
        15" hemlock stump S.82°W., 31.7 ft. OBT.  
Set - At corner point found orig. stone  
      1"x50" drill steel  
      30" Hemlock stump, (logged) bears North 7.8 ft. mkd: S13 BT  
      13" W.Fir stump (logged) bears South approx. 60.0 ft. mkd: S23 BT.  
Note - Logging road bears South 50 ft. East end of 30" metal culvert thru road bears North 153.0 ft. on slope distance.  
      Corner lies in clear cut high lead logging and no green trees left.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - July 1969 - C.S. File 54/91-26  
-----  
Found - Orig. corner & Markham's, which is a 1" drill steel by orig. corner stone. continued next page

TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 564400

PRIMARY CORNER DESCRIPTION CC Secs. 13 & 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Markham's rescribed tree stumps are now decaying and falling apart.  
Orig. 14" D.Fir, now 12" stump, N.18°W. 19.0 ft., shows scribing  
30" Hemlock, now stump, N. 7.8 ft., shows scribing.  
13" W.Fir, now stump, South approx. 60 ft., shows scribing.  
Because of the poor condition of this corner, we set Brass Cap.  
Set Brass cap at cor. mkd: COUNTY SURVEYORS T32S R3W  
OFFICE S 14 | S 13  
1969 S 23  
New BT - 5" Hemlock N.83°W., 55.0 ft. mkd: S14 CS BT  
New B0s- 5/8" I.Rod bears East 10.0'  
1" I.Pipe bears South 10.0'  
Note - This cor. lies north 50' & South 150' of a logging road in a logging unit.