TOWNSHIP 32 RANGE 03 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor- Under special instructions dated Aug. 20, 1912 - (DCSO records Vol. 20 Page(s) 8424)

Point for sec. cor. falls on a serpentine rock in place, 18x18x15" above ground on which I cut a cross (X) at exact point for cor. of secs. 23, 24, 25, & 26 with 2 notches S and 1 notch E of cross; from which:

A fir, 40" dia., bears N.7°E., 58 lks mkd: T32S R3W S24 BT
A cedar, 20" dia., bears S.44°E., 53 lks., mkd: T32S R3W S25 BT.
A fir, 40" dia. bears S.53°W., 14 lks mkd: T32S R3W S26 BT
A cedar, 20" dia., bears N.69°W., 31 lks., mkd: T32S R3W S23 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Aug. 1969 - C.S. File 54/91-73

Found - 18x18x15 Sone mkd: "+" & notches, firmly in place.
20", now 23" Cedar, N.69°W. 20.5 ft. shows good scar
40", now 45" D.Fir, N.7°E. 38.3 ft., shows good scar
40", now 45" D.Fir S.53°W. 9.2 ft., shows good scar.
20", now 24" Cedar, S.44°E. 35.0 ft. shows good scar.

Set Brass Cap at Cor. mkd: County Surveyors Office 1969

T32S	R3W
S 23	S 24
S 26	S 25

All Bearing Trees OK and Tagged.