

PRIMARY CORNER DESCRIPTION W. Closing Cor. for Secs. 19 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8539)

At point of intersection 12.06 chs. N. of the cor. of 24 and 25 only, T32S-R5W, I Set A Chinquapin post 3 ft. long, 4" sq., 24" in the ground for a closing corner of secs. 19 and 30, marked C C T32S R4W on E.; S19 on N.; and S30 on S. faces, with 2 grooves on S. and 4 grooves on N. faces; from which

A Madrona 8" dia., bears N.41°E., 27 lks. dist., marked T32S R4W S19 BT.

A Madrona 10" dia., bears S.30°E., 30 lks. dist., marked T32S R4W S30 BT.

This corner is on a N. slope, 100 ft. above ravine.

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #977 Surveyed, May/June 1979 - (DCSO records Vol. 43 Page(s) 16766)

Point for the closing corner of secs. 19 and 30, T32S R4W, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 23 ins. in the ground, with brass cap marked

T 32 S
R 5 W R 4 W
S 24 <u>S 19</u> CC
S 30
1979

from which

A Fir 18" dia., bears N.36°E., 94 lks. dist., mkd. T32S R4W S19 CC BT.

A Fir 6" dia., bears S.61°E., 46½ lks. dist., mkd. T32S R4W S30 cC BT.