

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8475)

-----  
Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which  
A Fir 20" dia., bears N.18½°E., 44 lks. mkd. ¼ S BT.  
A Fir 6" dia., bears S.72°W., 62 lks. mkd. ¼ S BT.  
This cor. is on a hillside, sloping SE., 50 ft. below top of spur.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - May 20, 1970 - C.S. File 54/114-38

-----  
Found - 6" now 12" D.Fir S.72°W., 40.9 ft., opened for scribe "¼".  
20" D.Fir, now snag, N.18½°E., 29.0 ft. shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office  
T 32 S R 4 W  
¼  $\frac{S \ 30}{S \ 31}$   
1970

New BTs -6" D.Fir N.51°W., 10.1 ft. mkd. ¼ S30 CS BT.  
6" D.Fir S.28°W., 24.9 ft. mkd. ¼ S31 CS BT.

Cor. Fd. and used in BLM survey by Roseberry in 1979, under Group #977 (DCSO records, Vol. 43 Page 16769)