

PRIMARY CORNER DESCRIPTION SE Cor. for Sec. 18 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8462)

-----  
Set post corner to secs. 17, 18, 19 and 20, from which  
A Fir 10" dia., bears N.40°E., 25 lks. dist.  
A Fir 36" dia., bears S.62°E., 76 lks. dist.  
A Fir 20" dia., bears S.55°W., 9 lks. dist.  
A Fir 16" dia., bears N.52°W., 26 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8542)

-----  
The cor. of secs. 17, 18, 19 and 20, which I reestablish as follows:  
Set a Fir post 3 ft. long, 4" sq., 24" in the ground for the SE. corner of sec. 18, marked T32S R4W S18 on NW. face; from which  
A Fir 16" dia., bears N.52°W., 26 lks. dist., mkd. T32S R4W S18 BT.

George J. Wenderoth - 1947-48 - C.S. File 38/246

-----  
Set 1½" I.Pipe.  
5" Chinquapin S.65°45'E., 37.8 ft.  
20" Fir S.59°26'W., 8.6 ft.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - May 12, 1970 - C.S. File 54/114-21

-----  
Found - 1½" Iron pipe at sec. cor. (See C.S. File 38/246)  
20" D.Fir now stump, S.59°W., 8.6 ft., opened for scribe.  
No trace of SE bearing tree. No trace of orig. BT.  
New BTs -20" D.Fir N.70°W., 10.6 ft. mkd. T32S R4W S18 CS BT.  
6" D.Fir N.1½°E., 26.2 ft. scribes CS BT.  
This corner lies in old cut unit, no other trees available.

BLM resurvey by Larry Evans, Cadastral Surveyor under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15332-33)

-----  
The SE. cor. of sec. 18 only, established by Byars in 1871 as common to secs. 17, 18, 19 and 20, changed Chapman and Nicklin in 1897 to sec. 18 only, determined at record distance from the faces of the remaining original 1871 bearing trees:  
(Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION SE corner Section 18 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A burned and decayed Fir snag 12" dia., bears N.44°E., 25½ lks. dist., with scribe marks S17 T32S R4W BT visible on partially opened double blaze. (Rec. N.40°E., 25 lks.)

A sawed Fir stump 29" dia., bears S.63½°W., 10½ lks. dist., no marks remaining. (Rec. S.55°W., 9 lks.)

A sawed Fir stump 26" dia., bears N.52°W., 26 lks. dist., no marks remaining.

and a bearing tree mkd. by Wenderoth in 1946:

A sawed Fir stump 28" dia., bears S.38°W., 11½ lks. dist., with scribe marks S18 CS BT visible on open double blaze.

and bearing trees mkd. by the County in 1970:

A Fir 6" dia., bears N.9°E., 38 lks. dist., with pitched over blaze.

A Fir 23" dia., bears N.73°W., 9½ lks. dist., with scribe marks T32S R4W S18 CS BT visible on partially healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 32 S R 4 W  
S 18 |  
S 20  
1971

From this point, a point established and recorded by Wenderoth in 1946, monumented with an iron pipe 1½" dia., protruding 6" above the ground, firmly set, bears S.65 3/4°E., 0.06 chs. dist.

Fd. OK, James Artman, March 16, 1990, M 109-66  
Found OK by R. Wytcherley, April 2003 See M142-35

FD. BC & accessories by K.DeGroot, 10/2010 - M157-32  
LAT: 42°46'59.206701" N. LONG: 123°12'29.383650" W.

Fd BC per M157-32 - 2/2020 by R Brown - M176-60