

PRIMARY CORNER DESCRIPTION Cor. for Secs. 7 & 18 only, on W. bdy. S17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8461)

Set a post corner to secs. 7, 8, 17 and 18, from which
A Pine 36" dia., bears N.5°E., 375 lks. dist.
No tree inside of limits in sec. 17.
An Oak 5" dia., bears S.40°W., 107 lks. dist.
An Oak 24" dia., bears N.5°W., 312 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8543)

The corner of secs. 7, 8, 17 and 18, I reestablish this corner as follows:
Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for corner of secs. 7 and 18, marked T32S S18 on SW.; and R4W S7 on NW. faces, with 4 notches on S. edge; from which
An Oak 5" dia., bears S.40°W., 107 lks. mkd. T32S R4W S18 BT.
An Oak 30" dia., bears N.5°W., 300 lks. mkd. T32S R4W S7 BT.

George J. Wenderoth, Deputy Co. Surveyor - 1946 - C.S. File 44/119

No sign of corner or BT set at intersection of line N-S & W. Drove 1" I.Pipe for the corner and scribed the following:
4" Live Oak bearing N.9°30'W., 38.1 ft.
4" Live Oak bearing S.15°57'W., 59.2 ft.

BLM resurvey by Larry Evans, Cadastral Surveyor under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15335-36)

The cor. of secs. 7 and 18 only, on W. bdy. of sec. 17, reestablished and recorded by Wenderoth in 1946, monumented with an iron pipe, 1" dia., protruding 10" above ground, firmly set. This point is accepted as the best available evidence of the position of the original corner.

from which bearing trees mkd. by Wenderoth:
A B.Oak 8" dia., bears S.15 3/4°W., 89 lks. with scribe marks CS S18 BT visible on decayed blaze.
A B.Oak 6" dia., bears N.9 1/2°W., 57 1/2 lks. with healed blaze.

At the corner point
(Cont. Next Page)

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Cor. for Secs. 7 & 18 only, W.bdy.S.17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
directly over iron pipe, with brass cap mkd: T 32 S R 4 W
S 7 | 17
S 18 |
1971

from which new bearing trees:

A Fir 14" dia., bears S.60°W., 40 lks. mkd. T32S R4W S18
BT.

A Fir 12" dia., bears N.50°W., 36 lks. mkd. T32S R4W S7 BT

Found OK by R.Wytcherley, April 2003 See M142-35

FD. BC & accessories by K.DeGroot, 10/2010 - M157-32
LAT: 42°47'51.330754" N. LONG: 123°12'30.122241" W.

BLM Dependent resurvey by Ernest Q. Lundeen, Cadastral
Surveyor, under Group No. 2790, surveyed July 2015 - (DCSO
records Vol. 58 Page(s) 23439)

The cor. of secs. 7 & 18 only, monumented with an iron post,
2½" dia., firmly set, projecting 4" above the ground, with
brass cap (properly) mkd.

from which bearing trees mkd. by Wendroth, in 1946

An oak snag, 11" dia., bears S.15¾°W., 58.7 ft., with a
healed blaze.

An oak, 7" dia., bears N.9½°W., 37.9 ft., with a healed
blaze.

and bearing trees mkd. by Evans in 1971

A fir, 26" dia., bears S.60°W., 26.4 ft., with a healed
blaze.

A fir, 26" dia., bears N.50°W., 23.8 ft., with a double
healed blaze.