

PRIMARY CORNER DESCRIPTION C C cor. Secs. 32 & 33 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8520)

The standard corner of secs. 32 and 33, which is a post, 4" sq., 24" above ground, marked and witnessed as described by the surveyor general.

Set a basalt stone 14 x 10 x 8 ins., 9" in the ground, for a closing corner of secs. 32 and 33, marked C C on N., with 2 grooves on W. and 4 grooves on E. faces; from which

A Fir 14" dia., bears N.18°E., 31 lks. dist., marked T32S R4W S33 BT.

A Fir 24" dia., bears N.17°W., 25 lks. dist., marked T32S R4W S32 BT.

This corner is on a NE. slope, 100 ft. above creek.

Douglas Co. Surveyors Office - John M. Powell, W. Penley and J. Heritage - May 19, 1970 - C.S. File 54/114-33

Found - No trace of stone monument.

14" now 21" D.Fir N.18°E., 20.5 ft. scribing visible on burnt face.

24" now 30" D.Fir N.17°W., 16.5 ft. shows good scar. OK.

Set Brass cap at cor. mkd: County Surveyors Office

T32S R4W CC S 32 | S 33

T33S R4W CC S 5

1970

Reblazed and rescribed:

21" D.Fir N.18°E., 20.5 ft. mkd. T32S R4W CC S33 CS BT.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #865, surveyed July/Oct. 1975 (DCSO records Vol. 42 Page(s) 16534)

The original closing corner of secs. 32 and 33, perpetuated and recorded by the County in 1970, monumented with an iron post, 1" dia., firmly set, projecting 18" above ground, with properly marked brass cap, from which the original bearing trees

A Fir 23" dia., bears N.18°E., 31 lks. dist., with illegible scribe marks visible on burned blaze.

Rescribed T32S R4W CC S33 CS BT on partially healed double blaze by the County Surveyors Office.

A Fir 33" dia., bears N.17°W., 25 lks. dist., with healed blaze.