

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 16 and 17

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8527)

Set a Pine post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. corner, marked 1/4 S. on W. face; from which
A Fir 8" dia., bears S.78°E., 29 lks. mkd. 1/4 S BT.
An Oak 6" dia., bears S.83°W., 6 lks. mkd. 1/4 S BT.
This 1/4 sec. corner is on the W. slope of spur, 100 ft. above creek.

George J. Wenderoth, Deputy Co. Surveyor - Wit: Frank Loso - April 1948 - (No record source found - information from former renewal record #37)

Found - 24" Fir S.73°45'E., 19.1 ft.
Oak stump S.83°W., 3.9 ft.
Drive 1 1/2" iron pipe and mark a new BT:
14" Pine S.64°35'W., 17.4 ft.

BLM resurvey by Larry Evans, Cadastral Surveyor under Group #736, surveyed May/June 1971 (DCSO records Vol. 37 Page(s) 15346-47)

The 1/4 sec.cor., perpetuated and recorded by Wenderoth in 1948, monumented with an iron pipe, 2" dia., protruding 4" above ground, firmly set, at record distance from the remains of the original 1897 bearing trees:

A root hole bears S.73 3/4°E., 29 lks. dist., alongside of which is a Fir 36" dia., with scribe mark 4 visible on partially opened blaze. (Rec. S.78°E.)

A root hole bears S.83°W., 6 lks. and a bearing tree mkd. by Wenderoth:

A Ponderosa Pine 17" dia., bears S.64 1/2°W., 27 lks. with scribe marks 1/4 S CS BT visible on partially healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 32 S R 4 W
1/4
S 17 S 16
1971

from which a new bearing tree

A Cedar 12" dia., bears S.55 1/4°E., 29 lks. mkd. 1/4 S16 BT.
Deposit iron pipe alongside iron post.