

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8526)

Set a Madrona post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. corner, marked 1/4 S on N. face; from which
A Fir 30" dia., bears N.69°E., 36 lks. mkd. 1/4 S BT.
A Fir 36" dia., bears S.17°E., 25 lks. mkd. 1/4 S BT.
This corner is on the W. slope of spur, 50 ft. below top.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - May 6, 1970 - C.S. File 54/114-12

Found - 30" now 38" D.Fir N.69°E., 23.8 ft., opened for scribe "1/4"
36" now 46" D.Fir S.17°E., 16.5 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T 32 S R 4 W
1/4 S 16
S 21
1970

Reblazed and rescribed:
38" D.Fir N.69°E., 23.8 ft. mkd. "1/4 S16 CS BT".

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, Group No. 2141, surveyed April/July 2006 - (DCSO records Vol. 55 Page(s) 21397)

The 1/4 sec. cor. of secs. 16 & 21, perpetuated by the Douglas County Surveyor's Office in 1970, monumented with an iron post, 1 1/4" dia., firmly set, top 4 ft. below the ground, with 2 1/2" dia. brass cap mkd. COUNTY SURVEYORS OFFICE T 32 S S 16 1/4 S 21 R 4 W 1970.

The original remaining bearing trees are now obliterated. Only the southeast bearing tree remains, downed and moved from its original position.

At the corner point
Set a stainless steel post, 28" long, 2 1/2" dia., 27" in the ground, directly over the iron post, in a collar of stone, with brass cap mkd. T 32 S R 4 W
S 16
1/4 S 21
2006

from which new bearing trees
A madrone, 12" dia., bears S.4°E., 59.7 ft. mkd. 1/4 S21 BT
continued next page

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A D.Fir, 11" dia., bears S.64 $\frac{3}{4}$ °W., 37.4 ft., mkd. $\frac{1}{4}$ S21 BT
Deposit a magnet in a white plastic case at the base of the
stainless steel post.
Latitude 42°47'05.87"N
Longitude 123°10'54.39"W
(NAD 1983 (CORS 96))

Ron Quimby - Crew: N. Fromdahl & J. Ogden - 6/2019 - C.S.
File 65/102-60

Found - BLM brass cap (properly mkd)
13" Madrona S.4°E., 59.7 ft., vis. scar.
16" D.Fir S.64 $\frac{3}{4}$ °W., 37.4 ft., good scar.
New BTs- 6" Madrona N.6°E., 12.8 ft., scribed $\frac{1}{4}$ S16 BT.
4" Alder N.50°W., 9.5 ft., scribed $\frac{1}{4}$ S16 BT.
Note - Compass decl. 15 $\frac{1}{2}$ °E.