

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 33 and 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8508)

Set a basalt stone 14 x 8 x 8 ins., 9" in the ground for ¼ sec. corner, marked ¼ on W. face; from which
A Fir 8" dia., bears S.29°E., 57 lks. mkd. ¼ S BT.
A Live Oak 6" dia., bears S.7½°W., 70 lks. mkd. ¼ S BT.
This cor. is on the S. slope of spur, 250 ft. below top.

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #865, surveyed July/Oct. 1975 (DCSO records Vol. 42 Page(s) 16545)

The ¼ cor. of secs. 33 and 34, monumented with the original basalt stone, 14 x 8 x 8 ins., firmly set 9" in the ground, mkd. ¼ on W. face, from which the remaining original bearing tree:

A Live Oak 8" dia., bears S.5½°W., 67 lks. dist., with illegible scribe marks visible on partially healed blaze. (Rec. S.7½°W., 70 lks.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap
mkd: T 32 S R 4 W

1/4
S 33 S 34
1975

from which new bearing trees

A Fir 10" dia., bears S.76½°E., 50½ lks. mkd. ¼ S34 BT.

A Fir 6" dia., bears S.83°W., 54 lks. mkd. ¼ S33 BT.

Deposit corner stone alongside iron post.