

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 20 Page(s) 8457)

Set 1/4 sec. post, from which
A Fir 10" dia., bears N.40°W., 12 lks. dist.
A Laurel 8" dia., bears N.85°E., 9 lks. dist.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8506-07)

The 1/4 sec. corner; post destroyed; bearing trees standing, from which I reestablish this 1/4 sec. corner as follows:
Set a Fir post 3 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on W. face; from which
A Madrona 10" dia., bears N.88°E., 18 lks. mkd. 1/4 S BT.
A Fir 6" dia., bears N.40°W., 12 lks. mkd. 1/4 S BT.

GLO resurvey by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12777)

Point for the 1/4 sec. cor. of sec. 3, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked
1/4 S 3
T32S
R4W
1959
from which
A Cedar 16" dia., bears N.74°E., 12 lks. mkd. 1/4 S3 BT.
A Fir 14" dia., bears S.35°E., 53 lks. mkd. 1/4 S3 BT.

Douglas Co. Surveyors Office, Bruce R. Rogers, Deputy - For: Doug. Co. Parks Dept. - June 1965 - M 29-78

Found - BLM brass cap mkd. 1/4 S 4, 1960.
All BTs in good condition.
(Correspondence concerning this corner, See BLM letter in CS 63/166)
Set Brass cap alongside BLM cap mkd: 1/4 S 4 T32S R4W
County Surveyors Off. 1965
New BT - 10" Fir bears S.21°W., 37.3 ft. mkd. E1/4 S4 CS BT.

continued next page

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Troy Rambo - For: Seneca Jones Timber - July 2002 - M140-74

Found - 1959 BLM Brass cap with a DCSO brass cap along side.
Dead 16" Cedar, bears N.74°E., 12 lks.
25" DF bears S.35°E., 53 lks.
23" DF bears S.21°W., 37.3 ft.
Scribed- "¼ S4 BT" on a 5" DF, bears N.82°W., 13.5 ft.
"¼ S3 BT" on a 5" DF, bears N.10°E., 5.9 ft.