TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8468)

Set a basalt stone 12 x 8 x 8 ins., 8" in the ground for ¼ sec. corner, mkd. ¼ on N. face; from which
A Cedar 24" dia., bears N.46°W., 75 lks. mkd. ¼ S BT.
A Cedar 30" dia., bears S.19°W., 39 lks. mkd. ¼ S BT.
This ¼ sec. corner is toward the N. side of ridge.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12794)

The ¼ sec. cor., monumented with a basalt stone 12x8x8 ins., mkd. ¼ on N. face, from which the original bearing trees:
A Cedar snag 30" dia., bears N.46°W., 75 lks., mkd. BT on opened blaze.
A Cedar 36" dia., bears S.19°W., 39 lks., mkd. with a healed blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 20" in the ground, with brass cap mkd:

¼ S 26
S 35
T32S R4W
1959

from which a new bearing tree
A Fir 20" dia., bears N.80°E., 107 lks. mkd ¼ S26 BT.
Deposit basalt stone alongside iron post.

Fd. OK, G. Nygren, Nov. 1989, C.S. File 63/51

Bruce Shaner - For: Seneca Jones Timber Co. - July 2002 - M140-41 & C.S. File 65/44-7D

Found - 2½" iron pipe with a 3¼" brass cap (properly mkd.)
30" Cedar snag, now cut down, scribes visible on snag, bears N.46°W., 49.5 ft.
28" D.Fir, face overgrown, bears N.80°E., 70.6 ft.
36" Cedar, face overgrown, bears S.19°W., 25.7 ft.
New - 6 ft. steel fence post bears West, 1.0 ft.
Note - South of logging road about 300 ft.