

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8488)

Set a basalt stone 14x8x6 ins., 9" in the ground for ¼ sec. corner, marked ¼ on W. face; from which
A Fir 20" dia., bears N.70°E., 12 lks. mkd. ¼ S BT.
A Cedar 12" dia., bears S.88°W., 17 lks. mkd. ¼ S BT.
This cor. is on the SW. slope of spur, 100 ft. above creek.

GLO remonumentation by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12792)

The ¼ sec. cor. monumented with a basalt stone, 14x8x6 ins., firmly set, marked ¼ on W. face, from which the remaining original bearing tree:
A rotted Fir sutmp 24" dia., bears N.70°E., 12 lks. no marks remaining.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 16" in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd: ¼
S 14|S 13
T32S R4W
1959
from which new bearing trees
A Fir 6" dia., bears N.75°E., 38 lks. mkd. ¼ S13 BT.
A Fir 9" dia., bears N.61°W., 50 lks. mkd. ¼ S14 BT.
Deposit basalt stone alongside the iron post.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 2/19/2009 - C.S. File 67/28-19

Fd OK
Both BTs Alive.