

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Sec. 24 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664, dated May 23, 1896 (DCSO records Vol. 20 Page(s) 8378)

Set a basalt stone 14x8x8 ins., 9" in the ground for the ¼ sec. cor., marked ¼ S on W. face, from which
A Cedar 14" dia., bears N.80°E., 36 lks. dist., mkd. ¼ S BT.
A Cedar 20" dia., bears S.55°W., 37 lks. dist., mkd. ¼ S BT.
This cor. is on a hillside, sloping SE. 25 ft. below top of spur.

GLO survey by Fred Mensch under special Instructions dated August 20, 1912 (DCSO records Vol. 20 Page(s) 8395)

The ¼ sec. cor. of secs. 19 and 24 is a stone, firmly set, marked and witnessed as described by the Surveyor General. I now change this cor. to refer to Sec. 24 only, and re-witness as follows: From cor.
A Cedar 20" dia., bears S.55°W., 37 lks. dist., mkd. ¼ S24 BT.
A Fir 10" dia., bears N.44°W., 44 lks. dist., mkd. ¼ S24 BT.
I destroy the marks on former bearing tree referring to Sec. 19.

GLO resurvey by Hans W. Thielsen, under Group #'s 350 & 422, Surveyed, May/June 1959 - (DCSO records Vol. 30 Page(s) 12773-74)

The ¼ sec. cor. of sec. 24 only, monumented by Nicklin with a basalt stone, 14x8x8 ins., firmly set, marked ¼ on W. face, from which the only remaining original bearing tree:
A Cedar 30" dia., bears S.55°W., 37 lks. dist., mkd. ¼ S24 BT on open blaze.
At the corner point
Set an iron post, 28 ins. long, 2 1/2 ins. dia., 20 ins. in the ground, with brass cap marked
¼ S 24
R4W R3W
T32S
1959
from which a new bearing tree
A Fir 18" dia., bears N.42°W., 47 lks. dist., mkd. ¼ S24 BT.
Deposit basalt stone alongside iron post.