

TOWNSHIP 32 RANGE 04 POINT IDENTIFIER # 988030

PRIMARY CORNER DESCRIPTION Cor. #5, Mineral Survey #148

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by W. F. Briggs, U.S. Deputy Mineral Surveyor - For:
Green Mountain Mining Company - May 9, 1887 (DCSO records
Vol. 28 Page(s) 11824)

Set Post No. 5, from which
 A Matherone 6" dia., bears S.28°W., 32 lks. dist.
 A Matherone 6" dia., bears N.20°E., 13 lks. dist.

Survey by Terrence O. Nickerson, -For: Bureau of Land
Management, Preliminary survey, Medford District - Aug. 17,
1979 - C.S. File 58/206 and M 78-42

Found - No wood post found.
 10" Madrone bears N.20°E., 11.0 ft. with no visible
 marks. (Rec. N.20°E., 8.6 ft.)
 18" Madrone bears S.28°W., 20.0 ft. with no visible
 marks (Rec. S.28°W., 21.1 ft.)
Set 5/8" Iron rod, 24" long, 20" in the ground.
New BTs -25" Fir bears N.56 3/4°E., 28.6 ft. mkd. X BT.
 15" Fir bears S.8½°E., 8.6 ft. mkd. X BT.