

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; 25, 36 of T32-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - George W. Hyde and Wells Lake, under Contract #54 dated Feb. 19, 1855 (DCSO records Vol. 20 Page(s) 8552)

Set post, cor. to secs. 25, 30, 31 and 36, on creek bottom, from which

- A Laurel 5" dia., bears N.30°30'E., 164 lks.
- A Laurel 4" dia., bears N.43°W., 64 lks.
- A Laurel 4" dia., bears S.38°W., 62 lks.
- A Fir 6" dia., bears S.61°E., 33 lks.

GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #729, dated Dec. 24, 1900 (DCSO records Vol. 20 Page(s) 8620-21) (Special instructions dated Sept. 12, 1901)

The Sec. cor., having disappeared, I mark a Fir 10" dia., for cor. of sec. 25, 30, 31 and 36, T32S 30 on NE.; R5W S31 on SE.; S36 on SW.; and R6W S25 on NW. sides, with 5 notches on N., and 1 notch on S. sides, from which

- A Fir 8" dia., bears N.10°E., 8 lks. mkd. T32S R5W S30 BT.
- A Fir 6" dia., bears S.61°E., 33 lks. mkd. T32S R5W S31 BT
- A Fir 12" dia., bears S.40°W., 18 lks. mkd T32S R6W S36 BT
- A Fir 7" dia., bears N.83°W., 50 lks. mkd T32S R6W S25 BT

The only green original witness tree now standing is the SE bearing tree; the others are new ones I marked in place of the original decayed ones.

Survey by George Wenderoth - For: Chester Smith - April 1949 - C.S. File 40/28 and M 32-2

- Found - 16" Fir for corner.
14" Fir N.10°E., 5.3 ft.
14" Fir N.83°W., 33.0 ft.
14" Fir S.40°W., 11.9 ft.
30" Fir, stump, S.61°E., 21.8 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey; S.A. Bilow, crew - Sept. 1958 - C.S. File 49/91-2

Found - All BTs and corner tree as recorded by Thiel in 1901. All are now snags. All check for bearing and distances. Find good scribing on all BTs, except SE BT and it shows old and rotted face.

I pull corner tree over and set Brass cap alongside base, mkd
County Surveyors Office

T 32 S
R6W

S25	S30
S36	S31

 R5W
1958

continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; & 25, 36 of T32-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs - 25" Cedar bears N.14°W., 69.5 ft. scribed S25 T32S
R6W CS BT.
10" Cedar bears S.34°W., 72.1 ft. scribed S36 T32S
R6W CS BT.
8" R.Fir bears S.80°E., 57.0 ft. scribed S31 T32S
R5W CS BT.
8" R.Fir bears N.69°E., 80.1 ft. scribed S30 T32S
R5W CS BT.

Douglas Co. Surveyors Office - John Powell, Frank Jones, Joe Brady, crew - July 1967 - C.S. File 53/52-47

Found - 1958 County brass cap.
25" Cedar now 27" N.14°W., 69.5 ft., shows scribe.
10" now 12" Cedar, S.34°W., 72.1 ft., shows scribe.
8" now 11" D.Fir N.69°E., 80.1 ft., shows good face.
SE BT was taken out by gas line.
New BT - 18" D.Fir S.87°E., 72.5 ft. mkd. T32S R5W S31 CS BT.
This corner lies West edge of gas line.

Fd. OK, August 1990, M 110-48

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 8/26/1999 - C.S. File 66/12-16

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 7" above ground. 1958
25" now 28" dia., down Cedar with an unhealed blaze, scribing visible "T32S R6W S25 CS BT" bears N.14°W., 69.5 ft. (agrees with rec.) 1958
10" now 16" dia., 2½ ft. high Cedar stump with a fully healed double blaze, bears S.34°W. 72.1 ft. (agrees with rec.) 1958
8" now 24" dia., D.Fir with a fully healed blaze bears N.69°E., 80.1 ft. (agrees with rec.) 1958
18" now 25" dia., D.Fir with a fully healed blaze bears S.87°E., 72.5 ft. (agrees with rec.) 1967
New BTs- 10" Pine double blazed & scribed "T32S R6W S25 CS BT" bears N.40½°W., 42.4 ft.
9" dia., Pine double blazed & scribed "T32S R5W S31 CS BT" bears S.5½°E., 29.9 ft.
Note - Corner lies along the Westerly edge of gas line road. New clear cut in SW quad.

continued next page

TOWNSHIP 32 RANGE 05 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; 25, 36 of T32-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Arthur R. Rambo, & Francis Simon
Cadastral Surveyors under Group No. 2143, surveyed May
2006/Feb. 2007 - (DCSO records, Vol. 55 Page(s) 21684-5)

The cor. of secs. 25, 30, 31, and 36, on the W. bdy. of the
Tp., perpetuated from original evidence no longer in
existence by the Douglas County Surveyor's Office, in 1958,
in 1967, and in 1999, monumented with an iron post, 1½" dia.,
firmly set, projecting 10" above the ground, with brass cap
(properly) mkd.

from which remains of bearing trees mkd. by the Douglas
County Surveyor's Office, in 1958

A fir, 28" dia., bears N.68¾°E., 80.3 ft., with a healed
blaze.

A sawed cedar stump, 23" dia., bears S.31¼°W., 72.0 ft.,
with a healed blaze.

A root hole, bears N.14°W., 69.5 ft., alongside of which
is an uprooted sawed cedar stump, 32" dia., with a
healed blaze.

and a bearing tree mkd. by the Douglas County Surveyor's
Office, in 1967

A fir, 29" dia., bears S.87¾°E., 73.0 ft., with a healed
blaze.

and bearing trees mkd. by the Douglas County Surveyor's
Office, in 1999

A pine, 13" dia., bears S.6¾°E., 29.9 ft., with a healed
double blaze.

A pine, 14" dia., bears N.41°W., 42.5 ft., with a healed
double blaze.

Corner is located along westerly edge of a natural gas
pipeline right of way, bears N. and S.

Fd. BC by Bart Heichel, 12/2022 - M181-68